

Quote

RO Number	831410
Tag	T534

MERCEDES BENZ OF WALNUT CREEK
 1301 PARKSIDE
 WALNUT CREEK CA 94596
 Phone # (925)937-1655

Customer Information			Vehicle Information			
Customer #	Customer Name	Quote Date/Time	Year	Make	Model	Odometer
511032	Don	03/18/2019 12:26 PM	2007	MERCEDES-BENZ	SL550R	74763
Address			VIN		Last Service Date	
Phone #	Email Address		Advisor	Appt Promised: Date/Time		
			Jorge Gonzalez	Yes 03/18/2019 Waiting		

SERVICE REQUEST

Technician Number: 2567 Status: REVIEWED

G Oil Filter Housing leaking

Additional Recommendation	Qty	LT	Hrs	Unit Price	Price
Labor					
EG58 Oil Filter Housing - Reseal		CC			
Parts					
272-180-05-10 COMBINED FILTER - COOLER	1	CC			
272-203-01-80-GASKET	1	CC			
64					
026-997-67-45 O-RING	1	CC			
Q-1-03-0004 ANTICORROSION/ANTIFREEZE G48	1	CC			
10081 PARTS WASH	1	CC			

Pricing Summary

	Labor	Parts	M/L/S	Tax	Line Total
Estimate	737.88	239.00	0.00	19.72	996.60

SERVICE REQUEST

Technician Number: 2567 Status: REVIEWED

H BOTH FRONT TORQUE ARM BUSHINGS TORN (R).

Additional Recommendation	Qty	LT	Hrs	Unit Price	Price
Labor					
BOTH FRONT TORQUE ARM BUSHINGS TORN (R).		CC			
Parts					
211-333-29-14 HYDRO MOUNT	2	CC			
211-333-06-97 ELASTOMERIC CUP	4	CC			
220-333-00-71 SCREW	2	CC			
000000-00328 NUT	2	CC			
1					

Pricing Summary

	Labor	Parts	M/L/S	Tax	Line Total
Estimate	737.88	265.10	0.00	21.87	1,024.85

SERVICE REQUEST

Technician Number: 2567 Status: REVIEWED

I	MIDDLE UNDER BODY PANEL MISSING.				
Additional Recommendation				Qty LT	Hrs Unit Price Price
Labor	MIDDLE UNDER BODY PANEL MISSING.			CC	
Parts					
	230-524-07-30 PANELLING		1	CC	
	230-528-00-09 PIPE		2	CC	
	001-990-60-36 SHEET METAL SCREW		4	CC	
	004-994-31-45 CLIP-TYPE NUT		4	CC	

Pricing Summary					
	Labor	Parts	M/L/S	Tax	Line Total
Estimate	98.88	323.34	0.00	26.68	448.90

SERVICE REQUEST
 Technician Number: 2567 Status: REVIEWED

J	ENGINE MOUNT SAGGING AND TRANS MOUNT COLLAPSED.				
Additional Recommendation				Qty LT	Hrs Unit Price Price
Labor	EN00 Mounts, Engine - Replace			CC	
Parts					
	230-240-04-17 ENGINE SUPPORT		2	CC	
	230-240-08-18 ENGINE SUPPORT		1	CC	

Pricing Summary					
	Labor	Parts	M/L/S	Tax	Line Total
Estimate	851.88	602.80	0.00	49.73	1,504.41

SERVICE REQUEST
 Technician Number: 2567 Status: REVIEWED

K	FOUND BOTH FRONT LOWER BALL JOINTS HAVE PLAY, REC REPLACEMENT.				
Additional Recommendation				Qty LT	Hrs Unit Price Price
Labor	FOUND BOTH FRONT LOWER BALL JOINTS HAVE PLAY, REC REPLACEMENT.			CC	
Parts					
	211-330-04-35 SUPPORTING JOINT		2	CC	
	000000-00328 NUT		2	CC	
	1				

Pricing Summary					
	Labor	Parts	M/L/S	Tax	Line Total
Estimate	851.88	350.80	0.00	28.94	1,231.62

Additional Recommendations	
Labor	\$3,278.40
Parts	\$1,781.04
Misc.	\$0.00
Lube	\$0.00

Sublet	\$0.00
Subtotal	\$5,059.44
Tax	\$146.94
Total	\$5,206.38