

Sun Motor Cars, Inc.

6677 Carlisle Pike

Mechanicsburg, Pennsylvania, 17050, US

Phone: 7176913333

mercedes.sunmotorcars.com

Repair Order #: **379835**

Tag #: **T2729**

Advisor: **Jon Herr** Advisor No. #: **1496**

Order Open Date: 2022-05-11

Customer Information

MORIN.RANDALL

1332 THE TER HAGERSTOWN, MD 21742-3232 Customer Number - 26620

Home Phone #: (301) 846-1451 Cell Phone #: (240) 313-0554

Contact Phone #:

Email Address: rmorin49@gmail.com

Vehicle Information

2015 MB SL400

VIN #: WDDJK6FA2FF032218

\$259.43

Color #: **799**

Mileage In/Out #: 30731/30735

Job # A Labor Total: \$ 259.43

PERFORM TRANSMISSION SERVICE 722.6, 722.9.

Cause.

Correction(s):

722TRANS PERFORM TRANSMISSION SERVICE 722.6, 722.9.

Tech Number: 2665 Labor Type: CM

Part Number	Part Description	Qty	List	Parts Total:	\$ 229.80
220-271-03-80	GASKET	1	\$ 26.00	\$ 26.00	
222-277-20-00	GEAR OIL FILTER	1	\$ 38.50	\$ 38.50	
001-989-77-03- USA8	MB GENUINE ATF 134FE 236.15 55 GAL DRUM	6	\$ 22.50	\$ 135.00	
222-271-00-97	PIPE	1	\$ 3.30	\$ 3.30	
007603-012102	RING,GENERAL,METAL	1	\$ 3.70	\$ 3.70	
004-990-35-12	SCREW	6	\$ 3.30	\$ 19.80	
99022 30731 PERFORMED	BRAKLEEN TRANSMISSION SERVI	1 CE	\$ 3.50	\$ 3.50	

Misc Total: No Charge

Job # A Total

\$ 489.23

Job # B Labor Total: \$ 0.00

Free inspection prior to expiration of CPO warranty

Correction(s):

803108 LOCK ELEMENT E FOR CENTRAL LOCKING SYSTEM REPLACE

(AFTER CHECK)

Tech Number: 2665 Labor Type: CM

\$0.00



Sun Motor Cars. Inc.

6677 Carlisle Pike

Mechanicsburg, Pennsylvania, 17050, US

Phone: 7176913333

mercedes.sunmotorcars.com

Repair Order #: 379835

Advisor No. #:

Tag #: T2729

Advisor: Jon Herr

Order Open Date: 2022-05-11

Qty Part Number Part Description List

Parts Total: \$ 0.00

1496

30731 PERFORMED MPI

Misc Total: No Charge

Job # B Total

\$ 0.00

Job # C **Labor Total:** \$ 0.00

CLIENT STATES THAT DRIVER'S SIDE MAGIC VISION WIPER DOESNT SEEM TO PUT ANY **WASHER FLUID OUT**

Cause:

Correction(s):

NPF CHECK CONDITION - NO PROBLEMS FOUND

Tech Number: 2665 Labor Type: CM

\$0.00

Part Number

Part Description

Qty

List

Parts Total:

\$ 0.00

30731 NO PROBLEM FOUND FUNCTION TESTED MAGIC WIPERS. BOTH WIPERS APPEAR TO HAVE NOMINAL OUTPUT OF WASHER FLUID. INSPECTED WASHER HOSES FOR ANY EXTERNAL LEAKS, NO LEAKS FOUND AT THIS TIME.

Misc Total:

No Charge

Job # C Total

\$ 0.00

lob # D **Labor Total:** No Charge

TECH NOTED ENGINE OIL LEAK FROM LEFT AND RIGHT FRONT CYLINDER HEAD COVERS

Cause: .. Correction(s):

WAR BOOK AND CODE WARRANTY REPAIR DO NOT CLOSE RO

Tech Number: 2665 Labor Type: WM08

No Charge

Part Number

Part Description

Qty

List

Parts Total: No Charge

000000-006365

HEXALOBULAR

BOLT

16

003-989-98-20-SEALANT MB

^{*} OEM means Original Equipment Manufacturer (factory) Parts | ** All parts are New unless specified otherwise.



Sun Motor Cars, Inc.

6677 Carlisle Pike

Mechanicsburg, Pennsylvania, 17050, US

Phone: 7176913333

mercedes.sunmotorcars.com

Repair Order #: **379835**

Tag #: **T2729**

Advisor: **Jon Herr**

Order Open Date: 2022-05-11

Advisor No. #:

·

30731 FAULTY SEAL NOTED LEFT AND RIGHT CYLINDER HEAD FRONT COVER SEALS LEAKING. REMOVED LEFT AND RIGHT SIDE CYLINDER HEAD FRONT COVERS. REMOVED OLD GASKET MATERIAL. CLEANED RESIDUAL OIL FROM ENGINE AND COVERS.

CLEANED AND PREPARED SEALING SURFACES. APPLIED NEW GASKET AND REINSTALLED FRONT COVERS

Misc Total: No Charge

Job # D Total

\$ 0.00

1496

RO Comments

Transmission fluid/filter changeFree inspection

prior to expiration of CPO warranty

Amount Totals

Total Labor: \$ 259.43

Total Parts: **\$ 229.80**

Miscellaneous + Discounts: \$ 50.00

OR CAT TAX Recovery: \$ 29.36

Shop Supplies: \$ 0.00

Customer Total:

\$ 468.59

Terms and Acceptance

Customer acknowledges approval of work described in this Repair Order Summary. Any Warranties on the product sold herein are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express including any implied warranty of merchantability or fitness for a particular purpose. and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

Please look for a survey on your service experience. The manufactures survey will be sent to you by email. If you are not sure if your current email address is on file please check with your service advisor.

We're working hard to make customers for life!

