### AR42.10-P-0010RK


Bleed brake system

03.05.2018

#### Model 231

#### **Modification notes**

31.08.2012	Entlüftungsschraube am Bremssattel	BA42.10-P-1005-10U



P42.10-2756-08

01 Filling and bleeding device

1 Cap

2 Brake fluid expansion reservoir

X	Remove		
	<b>Risk of death</b> caused by vehicle slipping or toppling off of the lifting platform.	Align vehicle between vehicle lift columns and position the four support plates at the vehicle lift support points specified by the vehicle manufacturer.	AS00.00-Z-0010-01A
⚠ Caution	<b>Risk of poisoning</b> from swallowing brake fluid. <b>Risk of injury</b> from skin and eye contact with brake fluid	Only pour brake fluid into suitable and appropriately marked containers. Wear protective clothing and eye protection when handling brake fluid.	AS42.50-Z-0001-01A
	Notes on repairs to brake system		AH42.00-P-0003-01A
	Brake fluid notes		AH42.50-P-0001-01A
1	Open engine hood		
1.	Clean		
2	Clean area around cap (1) of brake fluid expansion reservoir (2)		
	Preparation for bleeding procedure		
3	Unscrew cap (1) of brake fluid expansion reservoir (2)		
4	Fill with new brake fluid up to the "MAX" mark in the brake fluid expansion reservoir (2)	딸 Brake fluid	*BF42.10-P-1001-01J
5	Connect filler/bleeder unit (01) to brake fluid expansion reservoir (2) and switch on		
₩S	000 588 01 82 00 Filling unit		WS25.00-P-0016B
		<b>i</b> Pay attention to manufacturer's operating instructions.	
X	Remove		

6	Remove front wheel-and-tire assemblies		
₩AP			AP40.10-P-4050EW
	Bleeding		
7	Carrying out bleeding operation		AR42.10-P-0010-02RK
₩S	000 588 01 82 00 Filling unit		WS25.00-P-0016B
		Model 231Bleed screw on brake caliper	*BA42.10-P-1005-10U
		Me Bleed screw to brake caliper	*BA42.10-P-1002-12J
8	Switch off filler/bleeder unit (01) and remove from brake fluid expansion reservoir (2)		
9	Screw cap (1) onto brake fluid expansion reservoir (2)		
4	Check		
10	Check brake system for leaks		AR42.10-P-0100-01V
11	Check fluid level in brake fluid expansion reservoir (2); correct if necessary		
₩AP			AP42.10-P-4210V
Ж	Install		
12	Mount front wheel and tire assemblies		
₩AP			AP40.10-P-4050EW
13	Close engine hood		

# <sup>Nm</sup> Rear axle brake caliper

Number	Designation		Model 231
BA42.10-P-1002-12J	Bleed screw to brake caliper	Nm	18

## Mm Front axle brake caliper

Number	Designation			MODEL 231.474 except CODEB07
BA42.10-P-1005-10U	Bleed screw on brake caliper	Nm	18	18

# Mm Front axle brake caliper

Number	Designation		MODEL 231.474 with CODE B07	MODEL 231.479 except CODEB07
BA42.10-P-1005-10U	Bleed screw on brake caliper	Nm	18	18

# Mm Front axle brake caliper

		MODEL 231.479 with CODE B07	
BA42.10-P-1005-10U	Bleed screw on brake caliper	Nm	18

## Brake fluid

Number	Designation			Model 231
BF42.10-P-1001-01J	Brake fluid	Filling capacity	Liter	≈0,6
		Sheet		BB00.40-P-0330-01A
		Sheet		BB00.40-P-0331-00A