

**Wheel Works**  
**39270 Fremont Blvd.**  
**Fremont, Ca 94536**  
**(510) 797-8900**

Date **6/30/12 8:13 AM**

**Mercedes-Benz : 211 (E Class 2003-09 Sedan, 2004-09 Wagon) : Rear Wheel Drive : Sedan Steel Spring Suspension**  
**Europe version/USA : Standard Suspension (Code 954/954+485)**

**Front : Left**

Actual	Before	Specified Range
<b>-2.7°</b>		<b>-1.1° -0.5°</b>
<b>0.21°</b>		<b>0.03° 0.13°</b>
		<b>-2.32° -1.32°</b>

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

**Front : Right**

Actual	Before	Specified Range
<b>-1.4°</b>		<b>-1.1° -0.5°</b>
<b>-0.85°</b>		<b>0.03° 0.13°</b>
		<b>-2.32° -1.32°</b>

**Front**

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	Before	Specified Range
<b>-1.4°</b>		<b>-0.3° 0.3°</b>
		<b>-0.5° 0.5°</b>
<b>-0.64°</b>		<b>0.06° 0.26°</b>

**Rear : Left**

Actual	Before	Specified Range
<b>-2.6°</b>		<b>-1.5° -0.5°</b>
<b>0.09°</b>		<b>0.05° 0.29°</b>

Camber  
Toe

**Rear : Right**

Actual	Before	Specified Range
<b>-2.3°</b>		<b>-1.5° -0.5°</b>
<b>0.44°</b>		<b>0.05° 0.29°</b>

**Rear**

Cross Camber  
Total Toe  
Thrust Angle

Actual	Before	Specified Range
<b>-0.4°</b>		<b>-0.5° 0.5°</b>
<b>0.52°</b>		<b>0.22° 0.46°</b>
<b>-0.18°</b>		<b>-0.25° 0.25°</b>