

If fuel pumps are PN:  
211-470-00-00 this is  
the wrong connector.  
Striped wires should be  
on pins 2&3, not 1&3.  
Install adapter cable  
211-540-07-00 to  
correct the polarity.

