



CUSTOMER	VEHICLE	WORK ORDER ADMIN.
----------	---------	-------------------

	2004 Mercedes-Benz E55	WO # : 24730
	Plate : QVJ M96	Date : 04/22/2021
	ODO : 143,974	Time :
	V.I.N.: WDBUF76JX4A420632	PO # :
	Unit #:	REG # :
C#:  B#: 954	Engine: V8 5.5L 5439CC 332CI	Tech. : LUKE/REDSW3

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labor	Tx	Total	C
1.00		Valve Cover - Left	385.14	385.14		TAX	385.14	
1.00		Valve Cover - Right	427.70	427.70		TAX	427.70	
1.00		Breather Hose	15.40	15.40		TAX	15.40	
1.00		Breather Hose	67.00	67.00		TAX	67.00	
1.00		Breather Hose	7.97	7.97		TAX	7.97	
	3.00	Labor Times: Both Banks Valve Cover, Replace			387.00	TAX	387.00	
<b>Sub. Total: 1,290.21</b>						<b>TAX</b>		
1.00		Rear Crank seal	36.20	36.20		TAX	36.20	
	5.50	Labor Times: Rear Crankshaft Main Bearing Seal, Replace			709.50	TAX	709.50	
<b>Sub. Total: 745.70</b>						<b>TAX</b>		
2.00		Oil Drain Plug	9.18	18.36		TAX	18.36	
1.00		Trans Oil Filter Kit	34.16	34.16		TAX	34.16	
	1.90	Labor Times: E-Class Fluid Pan, Replace			245.10	TAX	245.10	
<b>Sub. Total: 297.62</b>						<b>TAX</b>		
2.00		Front Lower Ball Joint	37.29	74.58		TAX	74.58	
2.00		Front Upper Ball Jolint	90.60	181.20		TAX	181.20	
	1.80	Labor Times: Both Sides Ball Joint, Replace			232.20	TAX	232.20	
<b>Sub. Total: 487.98</b>						<b>TAX</b>		
1.00		Thrust Arm Left	319.36	319.36		TAX	319.36	
1.00		Thrust Arm Right	291.09	291.09		TAX	291.09	
	1.60	Labor Times: Both Sides Radius Arm, Replace			206.40	TAX	206.40	
<b>Sub. Total: 816.85</b>						<b>TAX</b>		
1.00		Control Arm F Right Lower	252.84	252.84		TAX	252.84	
1.00		Control Arm F Left Lower	249.60	249.60		TAX	249.60	

NO WARRANTY ON CUSTOMER SUPPLIED PARTS

Sub Tot.	4,541.45	3,945.80	8,487.25
		TAX	594.11
		TX2	0.00
		Deductible	0.00
		Total	9,081.36
Page		Amt. Paid	0.00
1 of 3		Amt. Owing	9,081.36



CUSTOMER	VEHICLE	WORK ORDER ADMIN.
----------	---------	-------------------

[REDACTED]	2004 Mercedes-Benz E55	WO # : 24730
[REDACTED]	Plate : QVJ M96	Date : 04/22/2021
[REDACTED]	ODO : 143,974	Time :
[REDACTED]	V.I.N.: WDBUF76JX4A420632	PO # :
[REDACTED]	Unit #:	REG # :
[REDACTED]	Engine: V8 5.5L 5439CC 332CI	Tech. : LUKE/REDSW3

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labor	Tx	Total	C
	2.60	Labor Times: Both Sides Control Arm, Replace			335.40	TAX	335.40	
		<b>Sub. Total: 837.84</b>				<b>TAX</b>		
2.00		Motor Mounts	123.36	246.72		TAX	246.72	
1.00		Trans Mount	97.53	97.53		TAX	97.53	
	6.50	Labor Times: All Mounts Engine Mount, Replace			838.50	TAX	838.50	
		<b>Sub. Total: 1,182.75</b>				<b>TAX</b>		
2.00		Driveshaft Flex Joint	213.44	426.88		TAX	426.88	
1.00		Center Bearing - Driveshaft	52.56	52.56		TAX	52.56	
	3.30	Labor Times: Rear Axle Drive/Propeller Shaft, R&R			425.70	TAX	425.70	
		<b>Sub. Total: 1,034.14</b>				<b>TAX</b>		
1.00		Brake Pads - Front	302.82	302.82		TAX	302.82	
2.00		Brake Discs - Front	185.00	370.00		TAX	370.00	
2.00		Brake Discs - Rear	150.00	300.00		TAX	300.00	
1.00		Brake Pads - Rear	219.40	219.40		TAX	219.40	
1.00		Brake Wear Sensor - F. Left	14.59	14.59		TAX	14.59	
2.00		Brake Wear Sensor - F. Right	10.07	20.14		TAX	20.14	
	3.00	Labor Times: Replace Brakes All Axles			387.00	TAX	387.00	
		<b>Sub. Total: 1,613.95</b>				<b>TAX</b>		
8.50		5w30 Full Synthetic - 1 Liter	8.98	76.33		TAX	76.33	
1.00		Oil Filter	18.88	18.88		TAX	18.88	
	0.50	Oil Service			50.00	TAX	50.00	

NO WARRANTY ON CUSTOMER SUPPLIED PARTS

Sub Tot.	4,541.45	3,945.80	8,487.25
		TAX	594.11
		TX2	0.00
		Deductible	0.00
		Total	9,081.36
Page		Amt. Paid	0.00
2 of 3		Amt. Owing	9,081.36



CUSTOMER	VEHICLE	WORK ORDER ADMIN.
----------	---------	-------------------

[REDACTED]	2004 Mercedes-Benz E55	WO # : 24730
[REDACTED]	Plate : QVJ M96	Date : 04/22/2021
[REDACTED]	ODO : 143,974	Time :
[REDACTED]	V.I.N.: WDBUF76JX4A420632	PO # :
[REDACTED]	Unit #:	REG # :
C#:415-312-7906 B#:954	Engine: V8 5.5L 5439CC 332CI	Tech. : LUKE/REDSW3

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labor	Tx	Total	C
		Sub. Total: 145.21				TAX		
1.00		Shop Supplies	35.00	35.00		TAX	35.00	

WO# 24730 Copyright 2021 Autogence Inc. - LANKAR 11.13.0

**This quote includes everything we have determined the vehicle needs so far.**

**Please note that price is subject to change slightly, due to limited parts availability and pricing fluctuations from suppliers, due to current market conditions.**

\*\*\*\*\*

Please leave us a review on [Yelp](#), [Google](#), or [Facebook](#)

Like us on [Facebook](#)

Follow us on [Instagram](#)

Thank you for your business!

PAID BY:...

NO WARRANTY ON CUSTOMER SUPPLIED PARTS

Sub Tot.	4,541.45	3,945.80	8,487.25
		TAX	594.11
		TX2	0.00
		Deductible	0.00
		Total	9,081.36
Page		Amt. Paid	0.00
3 of 3		Amt. Owing	9,081.36