

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle &gt; Technical Service Bulletins

## HANDS-FREE ACCESS TEMPORARILY NONFUNCTIONAL



Mercedes-Benz

# - Hands-free access temporarily nonfunctional -

Topic number	LI80.61-P-069910
Version	1
Function group	80.61 Keyless-Go/Keyless-Entry
Date	06-07-2019
Validity	Model series 222 facelift, model series 213 with code 871 (HFA)
Reason for change	

## Complaint

Hands-free access (HFA) may be temporarily nonfunctional or functional only after several clicks.

## Cause

May be due to the HFA control unit.

## Remedy

Install HFA control unit with part number A167 905 02 00 or successor and then perform SCN coding of HFA control unit.

## Symptoms

### Symptom

Overall vehicle / Safety and locking system / Keyless go / Function / Vehicle does not open