

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

INDICATOR LAMP OF A/C BUTTON IN FRONT CLIMATE CONTROL OPERATING UNIT INOPERATIVE



Mercedes-Benz

- Indicator lamp of A/C button in front climate control operating unit inoperative -

Topic number	LI83.30-P-067427
Version	2
Function group	83.30 Air conditioning
Date	12-22-2017
Validity	Model series 205, 213, 238, 253
Reason for change	Damage code adjusted.

Complaint

The indicator lamp of the A/C button in the operating unit of the front climate control is inoperative, although the air conditioning system is switched on. The air conditioning system functions correctly.

File	Designation
B.mp4	Clip

Cause

The LED in the A/C control panel may be damaged.

Remedy

Replace the A/C control panel.

WIS references

Document number	Title	Note	Allocation
AR83.30-P-6630LW	Remove/install front climate control operating unit	Validity: Model 205, model 213, model 253	Remedy
AR83.30-P-6630LWO	Remove/install front climate control operating unit	Validity: Model 238	Remedy

Symptoms

Symptom

Body / Air conditioning / Air conditioning / EC button lit
 Body / Air conditioning / Air conditioning / Air conditioning display error
 Body / Interior equipment / Switches, interior, general / Nonfunctional

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
					Reference EPC for A/C control unit part number.	
File						Designation
A.jpg						Picture

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
83-1917	REPLACE OPERATING UNIT OF AIR CONDITIONING SYSTEM		8340U52	Operating unit for automatic climate control does not operate correctly

A

