

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

MESSAGE IN INSTRUMENT CLUSTER "RADAR SENSOR SYSTEM SOILED, SEE OWNER'S MANUAL"



- Message in instrument cluster "Radar sensor system soiled, see Owner's Manual" -

Topic number	LI54.70-P-066764
Version	4
Function group	54.70 Proximity warning system
Date	10-31-2017
Validity	BR213 with code 258 BR238 with code 258
Reason for change	Remedy revised.

Complaint

The following message appears during vehicle operation: "Radar sensor system soiled, see Owner's Manual"

Note:

The following code (DTC) is logged in the ABA control unit (A108):

- C10C6FA

Cause

The ABA control unit may have become blocked due to soiling or a foreign object

Remedy

If the guided tests for DTC - C10C6FA - in XENTRY do not yield a result, then perform complete initial startup of the ABA control unit.

Note:

XENTRY DVD 09/2017 or newer must be installed for this.

All available addons must be installed.

Symptoms

Symptom

Communication/information / Warning and control system / COLLISION PREVENTION ASSIST /
Warning message in instrument cluster

Communication/information / Warning and control system / COLLISION PREVENTION ASSIST /
Warning system nonfunctional

Control unit/fault code

Control unit	Fault code	Fault code description
A108 - Active Brake Assist (ABA) (FCW213)	C10C6FA	The control unit 'COLLISION PREVENTION ASSIST' is blocked by dirt or by a foreign object. _

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A0009028737			Software (SW) for ABA/CPA/FCW213 control unit	1	The modified SCN coding is assigned to this software.	