

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

PARTIAL OPERATION OF INTERIOR AMBIENT LIGHTING



Mercedes-Benz

- Partial operation of interior ambient lighting -

Topic number	LI82.20-P-067044
Version	3
Function group	82.20 Interior lights
Date	12-14-2017
Validity	BR 213 code 808, 222 facelift and 238
Reason for change	Software available

Complaint

Operational complaints of ambient lighting and no fault codes are logged in the ambient lighting control unit.

Cause

Possibly Software

Remedy

Update software in ambient lighting control unit. The new software A2229026617 is available now with the following addons:

DVD09/17 with addon 8691

DVD07/17 with addon 8692

DVD12/17 with addon 8690

Symptoms

Symptom

Overall vehicle / Lighting / Interior illumination / Ambiance illumination / Does not go on

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A2229026617			Ambient lighting control unit software	1		