

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle &gt; Technical Service Bulletins

## INFORMATION LABEL ON TIRE SEALANT

## Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2020020001, February 2020

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Models Various**  
**Model Year 2016-2020****Information Label on Tire Sealant**

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 16-20 A-Class, C-Class, CLA-Class, E-Class, GLA-Class, GLC-Class, GLE-Class, GLS-Class, GT-Class, S-Class, SL-Class, SLC-Class (117, 156, 166, 167, 172, 177, 190, 205, 213, 217, 222, 231, 238, 253, 290, 292 platforms) vehicles, the enclosed tire sealant bottles (TIREFIT) might not meet current production specifications. A relevant information label might not be attached to the tire sealant bottle (TIREFIT). An authorized Mercedes-Benz dealer will attach the required information label to tire sealant bottle (TIREFIT) in the affected vehicles.

Prior to performing this Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired. Always Check VMI for any open campaigns, and perform accordingly.
- **VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.**
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 27,057 vehicles are affected.

Order No. P-SC-2020020001

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

## Service Campaign Bulletin


Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin


Service Campaign Bulletin

**Work procedure**

1. Remove tire sealant bottle (TIREFIT) from trunk.  
 For basic data, see **AP40.10-P-4054R**.
2. Cut open storage bag for tire sealant bottle (TIREFIT).

**Figure 1**

3. Remove tire sealant bottle (TIREFIT) and gloves from storage bag.
4. Position tire sealant bottle (TIREFIT) with the free area facing upward.

**Figure 2****Figure 3**

5. Subsequently attach information label (**A, Figure 3**) to tire sealant bottle (TIREFIT).

P-SC-2020020001

2

6. Place tire sealant bottle (TIREFIT) into the storage bag with the connection first (**B**, **Figure 4**).



**Figure 4**

7. Place gloves in storage bag.
8. Fold over the storage bag (**Figure 5**) and place it in the bracket in the vehicle's trunk with the open side facing downward.



**Figure 5**

P-SC-2020020001

Primary Parts Information

Qty.	Part Name	Part Number
1	Tire sealant information label	A 000 584 60 13

Warranty Information

**Operation:** Subsequently attach information label to tire sealant bottle (TIREFIT) (02-1322)

Damage Code	Operation Number	Labor Time (hrs.)
40 922 04 7	02-1322	0.1



Note

Operation Number labor times are subject to change

P-SC-2020020001