

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

NOISES FROM DYNAMIC SEAT



Mercedes-Benz

- Noises From Dynamic Seat -

Topic number	LI91.25-P-071314
Version	1
Function group	91.25 Multicontour seat (MKS)
Date	06-16-2020
Validity	MODEL 213 with code 432 (Active Multicontour Seat Package) MODEL 257 with code 432 (Active Multicontour Seat Package) MODEL 290 with code 432 (Active Multicontour Seat Package)
Reason for change	

Complaint

When the dynamic seat is activated, the tensioning straps on the seat backrest frame may creak.

Cause

The tensioning straps are in contact with the seat backrest frame and as a result, a creaking noise may occur.

Remedy

Apply lubricant (Krytox) between the tensioning strap and the seat backrest frame, see figures.

File

Bearbeitung Spannband 1.jpg

Bearbeitung Spannband 2.jpg

Designation

Processing of the stretch tape

Processing of the stretch tape

Symptoms

Symptom

Body / Seat / Seat adjustment / Noise

Body / Seat / Multicontour seat / Noise

Body / Seat / Active multicontour seat / Noise

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 000 989 36			Lubricant -			X
60			Krytox			


Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
---------	----------------	------	-------------	------

91N4136

91A4136

Bearbeitung Spannband 1



Bearbeitung Spannband 2

