

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty.

We also offer high quality non-OE parts that are suitable for your vehicle and fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP*." These non-OE (AP*) parts are not sourced from the vehicle's manufacturer or covered by its warranty. Non-OE parts come with a limited warranty backed by AutoNation and/or the parts manufacturer.

Dealer is not authorized to perform recall repairs for non-Dealer brand vehicles and Dealer's Vehicles Safety and Condition Inspection and/or service does not include a review of possible pending recalls or service campaigns issued by manufacturers of other makes and models.

Customer Copy

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL
 A CLIENT STATES THAT THERE IS AN OIL LEAK
 CAUSE: ELW INTACT AND AUTHORIZATION ATTACHED FOR 100% PARTS, LABOR AND HANDLING

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
11							
	8224	WMB					(N/C)
1	177-010-37-08		CRANKCASE COVER				(N/C)
13	004-990-44-12		SCREW PLUG				(N/C)
8	012-990-50-04		CAPSCREW W HEXAL. DRIVE				(N/C)
4	011-990-09-04		CAPSCREW W HEXAL. DRIVE				(N/C)
4	000-990-93-06		CAPSCREW W HEXAL. DRIVE				(N/C)
1	003-989-98-20-10		SEALANT MB				(N/C)
1	177-010-87-12		OIL SEPARATOR				(N/C)
1	177-010-88-12		OIL SEPARATOR				(N/C)
2	000-989-68-07-09-0109		MB 325.6 G40 ANTI FREEZE 1 GALLON 1 GAL				(N/C)
1	177-201-03-00-64		ELASTOMER MOLDED SEAL				(N/C)
1	177-201-09-00		ELASTOMER-MOLDED SEAL				(N/C)
1	177-140-04-00		VACUUM LINE				(N/C)
1	000-010-12-85		OIL FILLER CAP				(N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A:							0.00

39285 rear main seal leaking/ PTSS 000163209 case performed under vehicle inspection. confirmed costumers concern. found oil residue on gravel shields. proceeded to remove transmission housing plug to visually inspect inside for possible oil leak. confirmed oil inside. proceeded to check for PTSS case regarding concern. found 000163209 case regarding concern. recommended to replace rear main seal and replace both oil separators with new units. parked vehicle in neutral and released parking brake. disconnected battery. drained coolant. performed exhaust removal. removed gravel shields. removed heat shields. removed drive line. removed transmission from vehicle. removed and replaced rear main engine cover with new unit. installed removed components in reverse order. performed AC system recovery. recovered .42kgs. removed both left and right air filter element housings. disconnected AC condenser

<input type="checkbox"/> CASH	ORIGINAL ESTIMATE (PARTS & LABOR)	AUTHORIZED ADD'L REPAIRS	ADD'L REPAIRS OK'D BY	PHONE	SERVICE HOURS	LABOR AMOUNT	TOTALS
<input type="checkbox"/> CREDIT CARD	\$	\$	DATE	TIME		MONDAY - FRIDAY 7:30 A.M. - 6:30 P.M.	
ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE	ORIGINAL ESTIMATE (PARTS & LABOR)	AUTHORIZED ADD'L REPAIRS	ADD'L REPAIRS OK'D BY	PHONE	SATURDAY 8:00 A.M. - 4:00 P.M.	GAS, OIL, LUBE	
ALL PARTS WILL BE RESEARCHED UNLESS RESTRICTED OTHERWISE	\$	\$	DATE	TIME	CLOSED SUNDAY	SUBLET AMOUNT	
<input type="checkbox"/> SAVE	ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF ANY INCREASE IN THE ORIGINAL ESTIMATED PRICE AND RECEIPT OF A COPY THEREOF. PLEASE READ REVERSE SIDE					MISC. CHARGES	
	CUSTOMER SIGNATURE X					TOTAL CHARGES	
	Notice to Consumer: Please read important warranty information on back.					LESS INSURANCE	
						SALES TAX	
						PLEASE PAY THIS AMOUNT	