



MODEL 203 with CODE (612b) Xenon headlamp unit



P54.18-2993-09

- 1 Rear axle headlamp range adjustment sensor wiring harness
- 2 Clip
- 3 Connector
- 4 Bracket
- A51 Rear axle sensor (headlamp range adjustment)



P54.18-2995-09

- 10 Plug position B
- X62/8 Rear axle multiple circuit junction connector

🔍 🔍	Removing, installing		
1	Press out clip (2)	i Press clip (2) out of rear axle headlamp range adjustment sensor (A51).	
2	Unplug connector (3)		
3	Unclip bracket (4)		
4	Unplug connector from plug position B (10)	i In the housing of the rear axle multiple circuit junction connector (X62/8).	

5	Expose and remove rear axle headlamp range adjustment sensor wiring harness (1)		
6	Install in the reverse order		