

Auxiliary repair materials

Number	Designation	Order number
BR00.45-Z-1075-02A	<p>Terson double-sided adhesive tape For bonding trim strips and emblems (UV-resistant and weatherproof, black) (Width: 12 mm) Order no.: 107.64 A (Width: 19 mm) Order no.: 107.96 K (Width: 25 mm) Order no.: 117.05 Y</p>	<p>Henkel Loctite Deutschland GmbH Arabellastrasse 17 81925 München Germany Tel. +49-89-9268-0 Fax + 49-89-9101978 www.Loctite.de</p>

- 1 Stick double-sided adhesive tape, width 25 mm, to entire reverse side of illuminated door sill molding control unit (1).

i Bonding surfaces must be pre-treated in accordance with adhesive tape manufacturer's instructions.

2.1 Vehicles without electronic transmission control control unit (N15/3):

- Glue on illuminated door sill molding control unit (1) to footrest as per picture and fasten with bolt and nut (see arrow).

i Bonding surfaces must be pre-treated in accordance with adhesive tape manufacturer's instructions.

2.2 Vehicles without electronic transmission control unit (N15/3):

- Glue on illuminated door sill molding control unit (1) to electronic transmission control control unit (N15/3).

i Bonding surfaces must be pre-treated in accordance with adhesive tape manufacturer's instructions.



P82.20-3143-03