Mercedes-Benz "B" Service Checklist

Vehicle Compartment

- 1. Inspect throttle cable
- 2. Check Tele Aid by making test call to response center
- 3. Check horn, headlamps, markers, hazard flashers and turn signals
- 4. Check warning/indicator lamps, illumination and interior lighting
- 5. Check headlamp cleaning system operation
- 6. Check windshield wipers, rear wiper and front and rear washer system
- 7. Check seat belts for damage and proper function
- 8. Reset FSS service reminder counter in instrument cluster
- 9. Replace EVAC system dust/pollen filters
- 10. Check and perform battery test

Wheels and Brakes

- 1. Check thickness of brake pads and discs by removing and reinstalling R/F wheel
- 2. Inspect tires for damage
- 3. Measure tread depth
- 4. Check and correct tire pressures, including spare in trunk.

Vehicle underbody

- 1. Visually check for leakage
- 2. Inspect condition of front axle ball joints and rubber boots
- 3. Inspect condition of steering mechanical components and rubber boots
- 4. Visually inspect the lower power steering hose

Engine Compartment

- 1. Visually check for leakage on major components
- 2. Change oil and filter (synthetic)
- 3. Check and correct fluid levels of engine cooling system (anti-freeze), brake fluid, power-steering fluid and windshield-washer fluid.
- 4. Check condition of poly v-belt
- 5. Lubricate throttle linkage while checking operation and condition
- 6. Lubricate catch, safety catch and hinges on engine hood

Front and Rear of Vehicle

- 1. Check headlamp aiming
- 2. Replace windshield wiper blades
- 3. Inspect wiper blade for rear window (if equipped)
- 4. Inspect level of rear window washer fluid and fill as needed.

BlueTEC Vehicles Only (Excludes "E" Class)

1. Drain reservoir and replenish with AdBlue fluid. Additional time and expense required to complete.

Approximate repair time is between 3.0 – 5.0 hours. Total costs vary depending on vehicle.

With every service performed and inspections completed, if additional work is needed at the time of repair or in the near future the guest will be advised.