

AUTOBAHN GARAGE

44901 Golf Center Parkway, Suite 1
 INDIO, ca. 92201
 (760) 347-3322 Fax: (760) 347-3320
 Writer: CESAR VAZQUEZ

INVOICE #3440

autobahn.garage@yahoo.com
 caautobahngarage.com
 BAR# BAR # ARD 271557

CUSTOMER: WALTER HUNTER 1308 CURTIS AVE SALTON CITY, CA. 92274 Cell: (310) 695-8451	YEAR: 2004 MAKE/MODEL: MERCEDES-BENZ CL-CLASS VIN: WDBPJ75J24A040701 ENGINE: 5.0L V8 SOHC 24V	TRANS/DRIVE: 7-SPEED AUTOMAT LICENSE/STATE: /CA MILES IN/MILES 241277/241277
--	--	--

In: 3/3/2022 Out: 3/10/2022

VEHICLE ISSUE #1: CUSTOMER STATES THAT SUSPENSION ON LEFT SIDE IS DOWN PLEASE CHECK AND ADVISE

TECH REPORT: VERIFIED SUSPENSION SAGGING AT LEFT SIDE . FOUND HYDRAULIC STEERING HOSE/LINE FOR SUSPENSION TO HAVE A MAJOR LEAK. PRESSURE CANNOT BUILD UP.

***RECOMMEND REPLACING HYDRAULIC PRESSURE HOSE/LINE AND RECHECKING HYDRAULIC SUSPENSION
 ***ENGINE LIGHT ON-RECOMMEND DIAG
 ***PASSENGER FRONT TIRE HAS CORDS SHOWING, RUBBER TREAD PEELING

ADV NOTES: CHECKED AND ADVISED CUSTOMER OF ESTIMATE AND AVISED MIGHT NEED MORE ADDITIONAL WORK HE DECLINED ANY FURTHER WORK

LABOR: BUELNA, SUSPENSION DIAGNOSTIC	\$130.00	LABOR
--------------------------------------	----------	-------

VEHICLE ISSUE #2: CUSTOMER REQUEST A VEHICLE INSPECTION (CUSTOMER DECLINED)

*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***

VEHICLE ISSUE #3: CUSTOMER REQUEST POWER STEERING LINE RE ATTACHED (CUSTOMER DECLINED)

TECH REPORT: COULD NOT FIND LOOSE POWERSTEERING HOSE,LINES ARE LEAKING,

ADV NOTES: CHECKED AND FOUND NO PWER STEERING FLUID LEAK, LEAKS ARE FROM HYDRUALIC SUSPENSION

LABOR: BUELNA, POWER STEERING LINE REATTACHED	LABOR
---	-------

*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***

VEHICLE ISSUE #4: RECOMMENDED PRESSURE HOSE LINES (CUSTOMER DECLINED)

ADV NOTES: CHECKED AND FOUND ALL 4 HOSES FOR LEFT SIDE HYDRUALIC SUSPENSION LEAKING FLUID, NEED TIO START WITH THIS AND THEN POSSIBLY REEVALUATE COULD HAVE OTHER SUSPENSION ISSUES. NEED TO GET SUSPENSION SYSTEM TO PRESSURIZE THEN CONTINUE WITH DIAGNOSIS. THANK YOU.

PART: 220 320 08 PRESSURE RELIEF VALVE - FOR HYDRAULIC SUSPENSION	NEW
58	
PART: 2209978282 HYDRUALIC HOSE	NEW
PART: 2203200272 HYDRAULIC HOSE FOR SUSPENSION LEFT SIDE	NEW
PART: 223201372 HYDRUALIC PRESSURE HOSE LEFT SIDE	NEW
PART: 220998582 PRESSURE HOSE HYDRUALIC LEFT SIDE	NEW
PART: 2203270215 ACCUMULATOR FOR SUSPENSION	NEW
LABOR: BUELNA, REPLACE ACCUMULATOR AND RELIEF VALVE	LABOR
LABOR: BUELNA, REPLACE ALL 4 HOSES FOR LEFT SIDE SUSPENSION	LABOR

*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***

VEHICLE ISSUE #5: RECOMMENDED CHECK ENGINE LIGHT DIAGNOSIS (CUSTOMER DECLINED)

Recommended Repairs: *** CUSTOMER DECLINED: CUSTOMER REQUEST A VEHICLE INSPECTION (\$0.00) *** CUSTOMER DECLINED: CUSTOMER REQUEST POWER STEERING LINE RE ATTACHED (\$0.00) *** CUSTOMER DECLINED: RECOMMENDED PRESSURE HOSE LINES (\$2,699.19) *** CUSTOMER DECLINED: RECOMMENDED CHECK ENGINE LIGHT DIAGNOSIS (\$130.00)	Labor/Jobs	\$130.00
	Parts	\$0.00
	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$130.00
Warranty: From the date of delivery for a period of 12 months or 12,000 miles, whichever comes first. This firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$40 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Tax @ 8.75%	\$0.00
	Total	\$130.00
	Payments	\$130.00
	Balance	\$0.00

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

AUTOBAHN GARAGE

44901 Golf Center Parkway, Suite 1
 INDIO, ca. 92201
 (760) 347-3322 Fax: (760) 347-3320
 Writer: CESAR VAZQUEZ

INVOICE #3440

autobahn.garage@yahoo.com
 caautobahngarage.com
 BAR# BAR # ARD 271557

CUSTOMER: WALTER HUNTER 1308 CURTIS AVE SALTON CITY, CA. 92274 Cell: (310) 695-8451	YEAR: 2004 MAKE/MODEL: MERCEDES-BENZ CL-CLASS VIN: WDBPJ75J24A040701 ENGINE: 5.0L V8 SOHC 24V	TRANS/DRIVE: 7-SPEED AUTOMATIC LICENSE/STATE: /CA MILES IN/OUT: 241277 241277
--	--	---

LABOR: BUELNA, DIAGNOSE CHECK ENGINE LIGHT	LABOR
*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***	

Recommended Repairs: *** CUSTOMER DECLINED: CUSTOMER REQUEST A VEHICLE INSPECTION (\$0.00) *** CUSTOMER DECLINED: CUSTOMER REQUEST POWER STEERING LINE RE ATTACHED (\$0.00) *** CUSTOMER DECLINED: RECOMMENDED PRESSURE HOSE LINES (\$2,699.19) *** CUSTOMER DECLINED: RECOMMENDED CHECK ENGINE LIGHT DIAGNOSIS (\$130.00)	Labor/Jobs	\$130.00
	Parts	\$0.00
Warranty: From the date of delivery for a period of 12 months or 12,000 miles, whichever comes first. This firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$40 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$130.00
	Tax @ 8.75%	\$0.00
	Total	\$130.00
	Payments	\$130.00
	Balance	\$0.00

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____

Date 3/15/2022