```
Module : ME 2.0/2.1
                    MB - Nr. : 029 545 34 32
                    Supplier : Bosch
             Hardware-Version: 48/99
             Software-Version: 31/99
            Diagnosis recogn: 1/08
                                mel.dxt
     0300 Off assessor / Off assessor Catalytic Converter noxious
  Verify the primary voltage of the ignition coil :
  -> While STARTER = ACTIVATED : 200-350 V
     and the resistance (IGNITION = OFF) : 0.9-1.4 Ohm
  Also check the wiring and connections.
  Also check the secondary voltage of the ignition coil :
  -> While STARTER = ACTIVATED : 8-20 KV
     (resistance can not be measured --> build in diode)
      0303 Off assessor Cyl.3/ Off assessor Cyl.3 Catalytic
  Verify the primary voltage of the ignition coil :
  -> While STARTER = ACTIVATED : 200-350 V
      and the resistance (IGNITION = OFF) : 0.9-1.4 Ohm
  Also check the wiring and connections.
  Also check the secondary voltage of the ignition coil :
  -> While STARTER = ACTIVATED : 8-20 KV
      (resistance can not be measured --> build in diode)

    Single diagnosis completed !

Single diagnosis Traction - Status: Module is not build in,
                                            or does not respond !
```

ME

Module Info :

Diagnosis terminated !