

VIN	WDBTK72FX7F221855	Model series/model designation	209.472
Order number		License plate	

Filter status: All control units

**EZS - Electronic ignition switch** - ✓ -

MB number	HW version	SW version	Diagnosis version	Pin
2095453308	34.2005	29.2005	0/9	101

**ME 9.7 - Motor electronics 9.7** - ✓ -

MB number	HW version	SW version	Diagnosis version	Pin
0034466940	45.05	08.09	10/21	101
FW number	FW number (data)	FW number (boot SW)		
0094489340	0064477440			

**ETC - Electronic transmission control** - f - **i**

MB number	HW version	SW version	Diagnosis version	Pin
0335457332	09.2004	13.2006	1/1	101
Serial number	FW number	FW number (data)	FW number (boot SW)	
2202702106	0054484810			

Code	Text	Status
0717	The signal from component Y3/8n1 (Turbine speed sensor (VGS)) is not available.	STORED
0718	Component Y3/8n1 (Turbine speed sensor (VGS)) is defective.	STORED

Event Text Status

