


MODEL 219.3







P72.10-3017-09

Shown on left power window

Window lifter 5 Cover 9 Nut 2 Door foil Cover

6 7 3 Inner door panel Nut M10/3 Left front power window motor 8 Right front power window


Bolt Nut M10/4 motor

| XX | Remove/install | | |
|------|---|--|---------------------|
| 1 | Remove door lining from left or right front door | | AR72.10-P-1000TX |
| 2 | Remove front door crank window | | AR72.10-P-1900TX |
| 3 | Loosen door foil (2) from inner door panel (3) and fasten to front door with suitable adhesive tape | Loosen door foil (2) only until access opening in inner door panel (3) is accessible. Refer to: ↓ | |
| | | Remove/install door foil (2) on front door | AR72.10-P-1010TX |
| 4 | Unscrew bolts (4) from left front power window motor (M10/3) or right front power window motor (M10/4) | Nm | *BA72.29-P-1001-01A |
| 5 | Loosen left front power window motor (M10/3) or right front power window motor (M10/4) from window lifter (1) with mounting wedge and place to one side with electrical line connected. | 3 | *110589035900 |
| | | installation: Coat gears on left front power window motor (M10/3) or right front power window motor (M10/4) with Isoflex Topas L 32. | *BR00.45-Z-1012-06A |
| 6 | Remove covers (5) at bottom on front door | | |
| 7 | Remove cover (6) at side on front door | | |
| 8 | Unscrew nuts (7) and nut (8) from window lifter (1) | i Installation: Centralize window lifter (1) in bottom mounts in front door. | *BA72.10-P-1010-01M |
| 9 | Loosen nut (9) from window lifter (1) | Nm | *BA72.10-P-1010-01M |
| 10 | Remove window lifter (1) through access opening in inner door panel (3) | | |
| 11.1 | Unscrew nut (9) from window lifter (1) | Only when replacing window lifter (1). | |
| 12 | Install in the reverse order | | |
| 13 | Normalize window lifter (1) | | |

| Number | Designation | Model 219.3 |
|--------------------|---|----------------|
| BA72.10-P-1010-01M | Nut, window lifter at inner door panel Nm | 9 |

Nm Electric side doors

| Number | Designation | Model 219.3 |
|--------------------|--|----------------|
| BA72.29-P-1001-01A | Bolt, front door power window motor Nm | 5 |



Mounting wedge

Repair materials

| Number | Designation | Order number |
|--------------------|----------------------------------|-----------------|
| BR00.45-Z-1012-06A | Lock cylinder grease spray 50 ml | A 002 989 06 51 |