


**Model 205**  
**Model 213**  
**Model 238.4**  
**Model 253**  
**Model 293**


**Modification notes**

28.02.2019	Special tool assembly wedge replaced by special tool long wedge.	Operation Step 3	AR68.30-P-4050-03LW
------------	--	------------------	---------------------

	Notes on safety-relevant components		AH00.00-Z-0019-01A
☒ ☒	<b>Remove/install</b>		
1	Completely open soft top.	Model 205.4, 238.4	
2	Remove sun visor	Model 205.4 Model 238.4	AR68.60-P-5480NKB AR68.60-P-5480LWO
3	Remove A-pillar trim.	Model 205.4, 238.4 Model 205.0/1/2/3, 213, 253, 293 ☒ Long wedge ☒ Model 205.0/1/2/3, 213, 253, 293 Clip remover	AR68.30-P-4050-03LW AR68.30-P-4050-03LWA <a href="#">*115589035900</a> <a href="#">*452589016300</a>
4	Install in the reverse order		



Long wedge



Clip remover