Fault Code Report

TOPDON

Customer Name: N/A
Technician Name: N/A

Time: 03/07/2024 08:22:17



Shop Name: N/A	Telephone: N/A
SN: 960659907977	Email: N/A
Service Fee:	Repair Order No: N/A
Address:	City: N/A
State/County: N/A	Country or region: N/A
Zip Code: N/A	Notes: scan#1
Make: Mercedes-Benz	Model: S-Class
Year: 2018	Displacement: 4L
VIN: WDDXJ8GB8JA032861	Odometer: 38112 km
Registration No. N/A	Vehicle Software Version: V10.68

Pre Scan 03/07/2024 08:22:17

System(1)	Status(7)
Read Fault Code	Fault 7

DTC

System	Code	Description	Status
Read Fault Code	B178313	Control unit "Actuation module, LED exterior lighting, left front" has a malfunction. There is an open circuit.	STORED
Read Fault Code	B17831C	Control unit "Actuation module, LED exterior lighting, left front" has a malfunction. The voltage value is outside the permissible range.	STORED
Read Fault Code	B17ED92	The output for the low beams has a malfunction. The function or the instruction is faulty.	STORED
Read Fault Code	B284C11	The sensor for the light distribution has a malfunction. There is a short circuit to ground.	STORED
Read Fault Code	B284C13	The sensor for the light distribution has a malfunction. There is an open circuit.	STORED
Read Fault Code	B284D71	The actuator motor for the light distribution has a malfunction. The actuator is blocked.	STORED
Read Fault Code	U016800	Communication with the electronic ignition lock has a malfunction	STORED

Customer N	Name:	

Technician Name:_	
Date:	