Parts Information

- Parts list -




Image ID: drawing_B33090000017

Part number	Designation/additional information	Qty
A 211 330 11 01	DRIVE SHAFT	1
ê	LEFT	
	E Code: M005;	
	Replaced by: A 211 330 17 01	
A 211 330 17 01	DRIVE SHAFT	1
ê t	LEFT	
	🖺 [697] PART IS ONLY OR ALSO SUPPLIED AS RECONDITIONED PART	
	∰ Code: M005;	
	Replaces: A 211 330 11 01	
A 203 357 03 82	* PULSE RING	1
ô	FRONT LEFT	
	E Code: M005;	
A 203 357 03 82	* PULSE RING	1
ô	FRONT RIGHT	
	E Code: M005;	
	A 211 330 11 01	A 211 330 11 01 DRIVE SHAFT Image: Code: M005; Image: Code: M005; Replaced by: A 211 330 17 01 DRIVE SHAFT Image: Code: M005; Image: Code: M005; Image: Code: M005; Image: Code: M005; Image: Code: M005; Image: Code: M005; Replaces: A 211 330 11 01 Replaces: A 211 330 11 01 A 203 357 03 82 * PULSE RING Image: Code: M005; Image: Code: M005; Image: Code: M005; Image: M005;

© Copyright 2022 Mercedes-Benz AG

Parts Information

ltem	Part number	Designation/additional information	Qty
30 A 203 990 00 03	A 203 990 00 03	SCREW	1
		PROPELLER SHAFT TO FRONT WHEEL HUB, LEFT	
		III Code: M005;	
		Replaced by: A 016 990 13 01	
30 A 016 990 13 01	A 016 990 13 01	COMBI-HEXAGON HEAD BOLT	1
		PROPELLER SHAFT TO FRONT WHEEL HUB, LEFT	
	■ [] Screw included in set of boots scope of supply		
		₩ Code: M005;	
	Replaces: A 203 990 00 03		
80 A 112 030 18 72		SHAFT	1
	a a a a a a a a a a a a a a a a a a a		
		Code: M005;	
90 N 900055 0303		* RETAINING RING	2
	(0)	30X2 ∰ Code: M005;	
	A 112 080 01 15		1
	A 112 980 01 15 ô	* DEEP-GROOVE BALL BEARING III Code: M005;	1
110	-	* SNAP RING	1
110	A 112 994 09 35	∼ SNAP RING ∰ Code: M005;	1
120	₩ N 000472 055000	RETAINING RING	1
120	N 000472 035000	55X2	I
		₩ Code: M005;	
130 A 210 334 (A 210 334 00 19	PROTECTIVE RING	1
100	X210 001 00 17	■ [402] NO LONGER AVAILABLE	·
200	A 211 330 12 01	DRIVE SHAFT	1
200	A 211 330 12 01	RIGHT	·
		₩ Code: M005;	
		Replaced by: A 211 330 18 01	
200 A 211 330 18 ₹	A 211 330 18 01	DRIVE SHAFT	1
	₹	RIGHT	
		🖹 [697] PART IS ONLY OR ALSO SUPPLIED AS RECONDITIONED PART	
		₩ Code: M005;	
		Replaces: A 211 330 12 01	
220	A 203 990 00 03	SCREW	1
		PROPELLER SHAFT TO FRONT WHEEL HUB, RIGHT	
		∰ Code: M005;	
		Replaced by: A 016 990 13 01	
220 A 016 990 13	A 016 990 13 01	COMBI-HEXAGON HEAD BOLT	1
		PROPELLER SHAFT TO FRONT WHEEL HUB, RIGHT	
		[] Screw included in set of boots scope of supply	
		III Code: M005;	
		Replaces: A 203 990 00 03	
230	A 112 994 09 35	SNAP RING	1
		∰ Code: M005;	
270	A 220 330 01 85	REPAIR KIT, BOOT	2
		(PARTS KIT) AXLE SHAFT BOOT, EXTERNAL	
		Code: M005;	
270 A 21	A 211 330 01 85		2
		(PARTS KIT) INNER AXLE SHAFT BOOT	