

















## Parts Information






















## Parts Information

## - Parts list -

<b>Vehicle</b>	WDDHF9BB0EA785261 (D04)	E 500 4MATIC
<b>Color</b>	890 - undefined	<b>Equipment</b>
FIN: WDD2120911A785261		<b>Assortment class</b>
<b>Group</b>	42 BRAKES	<b>Sub-group</b>

Item	Part number	Designation/additional information
10	A 212 430 31 30  	BRAKE BOOSTER PARTS KIT  Code: 804/805/806/807;
20	A 164 431 00 80  	* GROMMET VACUUM LINE AT BRAKE BOOSTER  Code: 804/805/806/807;
30	A 000 431 26 80 	* GASKET BRAKE BOOSTER ASSEMBLY TO FIRE WALL  Fault location 43003
40	N 000000 003175	NUT PEDAL ASSEMBLY TO FIRE WALL; M8
50	A 204 292 00 74	PIN BRAKE UNIT TO PEDAL ASSEMBLY  Code: -ME04;  Fault location 29014
70	A 006 542 25 18	PRESSURE SENSOR VACUUM SENSOR IN BRAKE UNIT  Fault location 43099
100	A 212 430 06 01  	TS MASTER BRAKE CYLINDER PARTS KIT  Code: 804/805/806/807;
110	A 164 431 02 80  	* GROMMET EXPANSION RESERVOIR TO MASTER CYLINDER

## Parts Information

Item	Part number	Designation/additional information
120	A 001 431 33 60  	* SEALING RING MASTER BRAKE CYLINDER AT BRAKE BOOSTER; 44 X 2.6
130	N 000000 003175  	* NUT MASTER BRAKE CYLINDER AT BRAKE BOOSTER; M8
150	A 212 430 01 02  	EXPANSION RESERVOIR  Code: 804/805/806/807;
160	A 202 430 00 14 	* CAP  Fault location 43014
170	A 000 431 43 34	SIEVE  Fault location 43046
180	A 164 431 00 42 	MOUNTING PLATE EXPANSION RESERVOIR TO MASTER CYLINDER  Code: 804/805/806/807;
200	A 212 430 37 29 	VACUUM LINE BRAKE BOOSTER TO PARTITION POINT  [414] THE OLD PART MUST NO LONGER BE INSTALLED  Code: (804/805/806/807)+-(M651/M276); Replaced by: <a href="#">A 212 430 49 29</a>
200	A 212 430 49 29  	VACUUM LINE BRAKE BOOSTER TO PARTITION POINT  Code: (804/805/806/807)+-(M651/M276); Replaces: <a href="#">A 212 430 37 29</a>
210	A 000 987 11 45 	* CAP ON CHECK VALVE
230	A 000 998 02 03	CLOSING GROMMET LOWER PART
250	A 212 430 05 29	VACUUM LINE FROM SEPARATION POINT TO INTAKE MANIFOLD  Code: M278/M157;  Fault location 43033
900	A 210 540 20 81	RECEPTACLE HOUSING BRAKE FLUID MONITORING SWITCH S11; 2-PIN MQS

## Parts Information

<b>Item</b>	<b>Part number</b>	<b>Designation/additional information</b>
905	A 022 545 24 26	CLUTCH, MECHANICAL VACUUM SENSOR B64/1; 3-PIN MLK1.2