AN31.10-P-8080GZU Retrofit trailer hitch 26.6.15

Model 164 with code 494 (US version)

Shown on model 164.1

3 Trailer hitch



P31.10-2844-06

| Ξ | Remove | | | |
|-------------|--|---|------------------|--|
| 1 | Remove trim from spare tire well | MODEL 164 | | |
| ≆ AR | | MODEL 164 (except 164.195) | AR68.30-P-4620GZ | |
| 2 | Remove lining on the right-hand side of the trunk | MODEL 164 as of 01.12.06 Only when installing trailer brake preinstallation. | | |
| ⇔ AR | | MODEL 164.1 | AR68.30-P-4800GZ | |
| ⇔ AR | | MODEL 164.8 | AR68.30-P-4800RT | |
| 3 | Fold down rear seats and remove covers | MODEL 164 as of 01.12.06 Only when installing trailer brake preinstallation. | | |
| 4 | Remove B-pillar trim at bottom left | MODEL 164 as of 01.12.06 | | |
| | | Only when installing trailer brake preinstallation. | | |
| ⊯ AR | | | AR68.30-P-4700GZ | |
| 5 | Remove cover below left of instrument panel | MODEL 164 as of 01.12.06 Only when installing trailer brake preinstallation. | | |
| ₽ AR | | | AR68.10-P-1500GZ | |
| 6 | Remove left front floor covering and intermediate bottom | MODEL 164 as of 01.12.06 Only when installing trailer brake preinstallation. | | |
| ¥ AR | | · | AR68.20-P-2050GZ | |
| 7.1 | Detach rear SAM control unit with connected lines from bracket | MODEL 164 with CODE 848 (Power side vent windows) | | |
| ⊯ AR | | · | AR54.21-P-1269GZ | |
| 7.2 | Remove rear SAM control unit and replace with unit compatible with trailer hitch | MODEL 164 except CODE 848 (Power side vent windows) | | |
| i≆°AR | | i The rear SAM control unit is no longer required. Fasten the rear SAM control unit only after installation of all the wiring harnesses onto the trailer hitch. | AR54.21-P-1269GZ | |
| 8 ⊯≅AR | Remove crossmember under rear bumper | i The crossmember under the rear bumper is no longer required. | AR88.20-P-2250GZ | |

| | Ta | | |
|-------------------|--|---|----------------------|
| 9 FAR | Remove electric fan | m Model 164 with engine 642 | |
| AII. | | i The electric fan is no longer required. | |
| | Modify | | |
| 10 | Add bumper cutout | | AN31.11-P-8080-02GZ |
| X | Install | | 7.1.0.1111 0000 0202 |
| | | | ANIO4 44 D 0000 0507 |
| 11 | Retrofit mechanical detachable parts | Screw/bolt, reinforcement arm to vehicle floor | *BA31.11-P-1001-01G |
| | | Bolt/nut, trailer hitch/reinforcement plate to rear center section | *BA31.11-P-1002-01G |
| | | Screw/bolt, trailer hitch to reinforcement arm | *BA31.11-P-1004-01G |
| 12 | Connect wiring harness | MODEL 164.1 up to model year 2009 MODEL 164.8 | AN31.19-P-8080-03GZA |
| | | MODEL 164.1 as of model year 2010 | AN31.19-P-8080-03GZB |
| 13 | Retrofit wiring harness for trailer brake | MODEL 164 as of 01.12.06 Only when installing trailer brake preinstallation. | |
| | | | AN31.19-P-8080-06GZ |
| 14 | Install new electric fan that is compatible with the trailer hitch | Model 164 with engine 642 | |
| F AR | | | AR20.40-P-5000GZB |
| 15 | Install bracket for rear SAM control unit | MODEL 164.1 up to 30.06.09 MODEL 164.8 | |
| | | Route trailer hitch wiring harness under the bracket. | |
| 16 | Fasten rear SAM control unit into place | | |
| ₽ AR | | | AR54.21-P-1269GZ |
| 17 | Position impact absorber onto cross member of trailer hitch (3) | | |
| 18 | Replace underride guard | MODEL 164 with CODE P94 (Appearance package), MODEL 164 with CODE P96 (Exterior Sports package) | |
| 19 | Install remaining parts | | |
| | Update Vehicle Documentation (VeDoc) | | |
| 20 | Enter special equipment into online vehicle data card | i Code 550 (Trailer hitch) | |
| 21 | Attach "Trailer hitch retrofitted as per AN31.10-P-8080GZU" under field organization text for design group 31 and design group 88. | | |
| 22 | Attach note "Trailer hitch retrofitted as per AN31.10-P-8080GZU" under field organization texts for design group 50. | Model 164 with engine 642 | |
| 23 | Attach note "Trailer hitch retrofitted as per AN31.10-P-8080GZU" under field organization texts for design group 54. | MODEL 164 except CODE 848 (Power side vent windows) | |
| 24 | Connect diagnostic system and select vehicle using vehicle identification number (VIN) | | |
| S A D | | | AD00.00-P-2000-04A |
| 25 | Carry out variant coding using software calibration number (SCN) | "Rear SAM control unit" "CGW control unit" Set the coding in the menu "Detect trailer" from "NOT AVAILABLE" to "AVAILABLE". | |
| 26 № AD | Disconnect diagnostic system | | AD00.00-P-2000-04A |
| 1 | Check | | 30.00 . 2000 0 11 (|
| 27 | Perform function test of ball neck and light | | AN31.10-P-0008-01A |
| | signals on trailer hitch socket | | |

Nm Trailer coupling mechanism

| Number | Designation | | ORIS trailer hitch | Model 164.1/8 WESTFALIA trailer hitch (accessories) |
|--------------------|--|----|--------------------|---|
| BA31.11-P-1001-01G | Screw/bolt, reinforcement arm to vehicle floor | Nm | 66 | 55 |

Nm Trailer coupling mechanism

| Number | Designation | Model 164.1/8 | Model 164.1/8 |
|--------|-------------|--------------------|---------------------|
| | | ORIS trailer hitch | WESTFALIA trailer |
| | | (standard) | hitch (accessories) |

| BA31.11-P-1002-01G | Bolt/nut, trailer hitch/reinforcement plate to rear center section | Nm | 66 | 55 |
|--------------------|--|----|----|----|
|--------------------|--|----|----|----|

Nm Trailer coupling mechanism

| Number | Designation | | Model 164.1/8 | Model 164.1/8 |
|--------------------|--|----|---------------|---------------------|
| | | | | WESTFALIA trailer |
| | | | (standard) | hitch (accessories) |
| BA31.11-P-1004-01G | Screw/bolt, trailer hitch to reinforcement arm | Nm | 120 | 95 |

Parts ordering note

| Part no. | Designation | Quantity |
|-------------------|------------------------------|----------|
| KG 99 (siehe EPC) | Trailer hitch parts kit | 1 |
| KG 99 (siehe EPC) | Trailer brake wiring harness | 1 |