



[Select Vehicle](#) | [New TSBs](#) | [Technician's Reference](#)

Component Search:


[Conversion Calculator](#)

2001 Mercedes Benz C 240 Sedan (203.061) V6-2.6L (112.912)

[Vehicle Level](#) → [Heating and Air Conditioning](#) → [Air Door](#) → [Air Door Actuator / Motor](#) → [Service and Repair](#) → [AR83.10-P-2002P Remove/Install Actuator For Left Blend Air Flap](#) ←

AR83.10-P-2002P Remove/Install Actuator For Left Blend Air Flap

AR83.10-P-2002P Remove/Install Actuator For Left Blend [Air Flap](#)



1 Remove cover below instrument panel

NOTE: Driver's side.

2 Unscrew screws (1)


NOTE: Three screws.

- See "**Special Tools**" given below.

3 Remove actuator motor for left blend [air flap](#) (M2/6) from AC/heater housing (2)

- 4 Disconnect connector (3) from actuator motor for left blend [air flap](#) (M2/6)
- 5 Install in the reverse order
- 6 Synchronize left blend air flap actuator motor (M2/6).

Special Tools



Zoom

Sized for Print