

Vehicle information

Benz 2002 163.113 ML270 Diesel

VIN: 4JGAB13E02A367386

Diagnostics time: 2023/11/17 09:52

Path: Automatic selection > Auto scan >

Status report

System name	DTC counts	Status
CDI 2-Common Rail Diesel Injection	0	Pass
ETC-Electronic transmission control	0	Pass
ESP-Electronic stability program	02	Fault
AB-Airbag	0	Pass
ICM-Instrument cluster with maintenance interval display	0	Pass
ESM-Electronic selector module	0	Pass
VG - Transfer case	0	Pass
BAS-Brake assist	0	Pass
EAM-Extended activity module	0	Pass
AAM-All Activity Module	01	Fault
-Drive authorization system	0	Pass
LCP-Lower operating panel with power window function	0	Pass
AUDIO	02	Fault
AAC-Automatic air conditioning	0	Pass

1. ESP-Electronic stability program —— (02)

- | | |
|--------------|---|
| 1.1. C1140-8 | Component 'N49 (Steering Angle Sensor (SAS))' is not initialized.
Stored |
| 1.2. C1120 | N64 (ESP Yaw Rate Sensor (YRS))
Stored |

2. AAM-All Activity Module — (01)**2.1. B1786-002**

The Central Locking (CL/ZV) signal contact Tailgate provides implausible values.- Fault during locking

Stored

3. AUDIO — (02)**3.1. N1141**

Set/actual configuration of Digital Data Bus (D2B) ring is different

Stored&Current

3.2. N1112

No data is transmitted between Digital Data Bus (D2B) master and Digital Data Bus (D2B) predecessor component

Stored&Current