





P88.70-2477-04


Operation no. of operation texts or standard texts and flat rates

Category	Op. no.	Operation text
P	025748	Lubricate folding mechanism of left and right outside mirror

Icon	Checking		
1	Check whether vehicle is affected	Part 1, model 164 from WDC1641201A017913 to WDC1641201A181795 Part 2, model 164 from WDC1641201A182015 to WDC1641221A073182 Part 3, model 164 from WDC1641221A073224 to WDC1641221A165784 Part 4, model 164 from WDC1641221A165789 to WDC1641752A046115 Part 5, model 164 from WDC1641752A046237 to WDC1641861A013073 Part 6, model 164 from WDC1641861A013077 to WDC1641862A194366 Part 7, model 164 from WDC1641862A194453 to WDC1648862A152302 Part 1, model 164 from 4JG1641221A116664 to 4JG1641751A063159 Part 2, model 164 from 4JG1641751A063163 to 4JG1641861A010360 Part 3, model 164 from 4JG1641861A010361 to 4JG1641861A024893 Part 4, model 164 from 4JG1641861A024895 to 4JG1641861A047528 Part 5, model 164 from 4JG1641861A047532 to 4JG1641861A060097 Part 6, model 164 from 4JG1641861A060099 to 4JG1641861A081020 Part 7, model 164 from 4JG1641861A081024 to 4JG1641861A099860 Part 8, model 164 from 4JG1641861A099864 to 4JG1641861A128867 Part 9, model 164 from 4JG1641861A128869 to 4JG1641861A170380 Part 10, model 164 from 4JG1641861A170389 to 4JG1641861A199119	SM88.70-P-0003-01A  SM88.70-P-0003-01B  SM88.70-P-0003-01C  SM88.70-P-0003-01D  SM88.70-P-0003-01E  SM88.70-P-0003-01F  SM88.70-P-0003-01T  SM88.70-P-0003-01G  SM88.70-P-0003-01H  SM88.70-P-0003-01I  SM88.70-P-0003-01J  SM88.70-P-0003-01K  SM88.70-P-0003-01L  SM88.70-P-0003-01M  SM88.70-P-0003-01N  SM88.70-P-0003-01O  SM88.70-P-0003-01P

		Part 11, model 164 from 4JG1641861A199121 to 4JG1648711A179418 Part 12, model 164 from 4JG1648711A179426 to 4JG1648711A211128 Part 1, model 251 from WDC2510201A036027 to WDC2511752A021510 Part 1, model 251 from 4JG2511221A033339 to 4JG2511651A011738 Part 2, model 251 from 4JG2511651A011739 to 4JG2511651A027087 Part 3, model 251 from 4JG2511651A027090 to 4JG2511651A045919 Part 4, model 251 from 4JG2511651A045931 to 4JG2511771A032714	SM88.70-P-0003-01Q  SM88.70-P-0003-01R  SM88.70-P-0003-01S  SM88.70-P-0003-01U  SM88.70-P-0003-01V  SM88.70-P-0003-01W  SM88.70-P-0003-01X
	<b>Remove/install</b>		
2	Push right outside mirror away to the front	 In direction of engine hood.	
3	Apply antifriction agent	 To guideway (1) of plastic slider. The required antifriction agent is a component of noise service case A 000 580 03 50.	
4	Move right outside mirror to starting position		
5	Fold right outside mirror out and in	 Repeat the process 10 times.	
6	Perform work procedure on left outside mirror		

#### Parts ordering notes

Part no.	Designation	Quantity
A 000 989 38 60	Antifriction agent  container holds enough for 200 vehicles	1