
$\fbox{i}$  The line (F) indicates the line the sealing compound is to be applied on.

 $\label{eq:seling_surfaces} \fbox{1} Sealing surfaces must be free of oil and grease. Apply sealing compound on the surface as a bead 1.5 mm (<math display="inline">\pm$  0.5 mm) wide. The sealing compound must be applied within 10 minutes. The sealing compound bead must not be spread.



P01.20-2140-05