

VIN	██████████	Model series/model designation	164.████
Order number		License plate	

Full list of fault codes and events

9000	Control unit N69/5 (Keyless Go control unit) is defective.
9040	M14/6 (Left front door central locking motor) , Engine opening assists : Limit switch PERMANENTLY ACTUATED
9045	M14/6 (Left front door central locking motor) , Engine opening assists : Limit switch NOT OPERATED
9060	M14/8 (CL left rear door motor) , Engine opening assists : Limit switch PERMANENTLY ACTUATED
9065	M14/8 (CL left rear door motor) , Engine opening assists : Limit switch NOT OPERATED
9080	M14/5 (Right front door central locking motor) , Engine opening assists : Limit switch PERMANENTLY ACTUATED
9085	M14/5 (Right front door central locking motor) , Engine opening assists : Limit switch NOT OPERATED
9100	M14/9 (CL right rear door motor) , Engine opening assists : Limit switch PERMANENTLY ACTUATED
9105	M14/9 (CL right rear door motor) , Engine opening assists : Limit switch NOT OPERATED
9110	A17/1 (Left front Keyless Go door handle) : PERMANENTLY ACTUATED
9111	A17/3 (Left rear Keyless Go door handle) : PERMANENTLY ACTUATED
9112	A17/2 (Right front Keyless Go door handle) : PERMANENTLY ACTUATED
9113	A17/4 (Right rear Keyless Go door handle) : PERMANENTLY ACTUATED
9118	A17/1 (Left front Keyless Go door handle) : Short circuit to positive
9119	A17/3 (Left rear Keyless Go door handle) : Short circuit to positive
911A	A17/2 (Right front Keyless Go door handle) : Short circuit to positive
911B	A17/4 (Right rear Keyless Go door handle) : Short circuit to positive
911C	A17/1 (Left front Keyless Go door handle) : Short circuit to ground / Signal faulty

12/2016 (2016-10-06)\AddOns: ([6988] (7160) (7258) (6755) (6933) (7418) (7176) (6765) (7292) (6726) (6832) (7030) (6815) (6961) (6892) (6927) (6642) (6882) (6977) (6604) (7100) (7128) (6819) (7134) (7069) (6785) (7229) (6669) (6658) (7309) (7188) (6728) (6569) (6843) (6826) (6818) (6997) (6896) (7172) (7092) (6931) (7084) (6951) (6835) (6691) (7014) (6622) (6792) (6828) (6768) (6985) (6721) (6745) (7154) (6677) (7143) (6817) (6919) (6780) (6707) (6686) (6863) (7002) (6991) (6700) (6615) (6803) (6880) (6580) (6646) (6576) (6986) (6814) (6670) (7009) (7018) (6781) (6673) (6877) (6864) (6872) (7033) (7256) (7318) (6730) (7104) (6663) (7147) (6798) (6994) (6858) (6898) (6871) (7386) (6704) (7029) (6822) (6850) (6796) (7065) (6802) (6971) (6874) (7072) (7082) (6746) (7239) (6772) (6857) (6949) (7180) (6831) (7086) (6627) (6916) (7206) (6742) (7042) (6964) (6870) (7166) (7138) (7080) (7398) (6848) (6975) (7001) (6760) (6679) (6845) (6732) (6565) (6941) (6902) (6890) (6847) (6842) (6856) (7359) (6578) (7007) (7185) (7158) (7026) (6894) (6980) (6739) (7119) (6684) (6995) (6816) (6809) (6784) (6972) (6633) (6952) (6648) (6943) (6793) (6981) (7135) (7036) (6608) (6907) (7023) (6861) (7113) (7433) (7209) (7324) (6954) (7097) (6705) (6825) (6968) (6885) (6616) (6573) (6759) (6676) (6682) (6887) (6910) (7226) (6914) (6866) (7360) (6886) (7233) (7108) (6953) (5226) (7267) (7121) (7201) (7063) (6599) (7049) (7216) (6649) (7055) (6774) (6724) (7225) (6990) (6833) (6965) (6906) (6800) (7251) (6962) (6958) (7068) (7071) (6900) (7316) (7289) (6788) (6851) (6709) (6948) (6983) (6769) (6714) (7190) (6924) (6889) (6921) (6911) (7012) (7150) (5225) (7164) (7198) (6588) (6903) (6697) (6596) (6839) (7058) (6790) (7109) (6787) (7052) (6868) (7300) (6653) (7248) (6884) (7032) (6735) (7046) (6876) (6630) (6806) (6904) (6659) (7458) (6867) (7008) (6946) (7184) (6879) (6841) (6912) (6570) (7142) (7077) (6801) (6618) (6976) (73131))

911D	A17/3 (Left rear Keyless Go door handle) : Short circuit to ground / Signal faulty
911E	A17/2 (Right front Keyless Go door handle) : Short circuit to ground / Signal faulty
911F	A17/4 (Right rear Keyless Go door handle) : Short circuit to ground / Signal faulty
9220	Tailgate , "Lock" button : PERMANENTLY ACTUATED
9350	Antenna not or not correctly connected
9361	A2/39 (Keyless Go antenna, left rear door) : Open circuit
9362	A2/41 (Keyless Go antenna, right rear door) : Open circuit
9363	A2/60 (Cockpit Keyless Go antenna) : Open circuit
9364	A2/35 (Keyless Go antenna, trunk) (W221), Tailgate (W164, X164, W251) : Open circuit
9371	A2/39 (Keyless Go antenna, left rear door) : Short circuit
9372	A2/41 (Keyless Go antenna, right rear door) : Short circuit
9373	A2/60 (Cockpit Keyless Go antenna) : Short circuit
9374	A2/35 (Keyless Go antenna, trunk) (W221), Tailgate (W164, X164, W251) : Short circuit
9381	At least one of the Keyless Go antennas has Short circuit to positive.
9382	At least one of the Keyless Go antennas has Short circuit to ground.
93A9	M14/6 (Left front door central locking motor) : Output 'Engine opening assists' is overloaded.
93AA	M14/8 (CL left rear door motor) : Output 'Engine opening assists' is overloaded.
93AB	M14/5 (Right front door central locking motor) : Output 'Engine opening assists' is overloaded.
93AC	M14/9 (CL right rear door motor) : Output 'Engine opening assists' is overloaded.
93AD	At least one of the door handles is not plugged in or cannot be tested.
93AE	A2/61 (Keyless Go antenna, interior) : Open circuit
93AF	A2/61 (Keyless Go antenna, interior) : Short circuit
Event 9010	Undervoltage supply :
Event 9011	Overvoltage supply :
Event 93B0	No CAN message was received from control unit EZS.

Filename: C:\Program
Files\Mercedes-Benz\DAS\bin\..\trees\pkw\fahrber\kg2\menues\mnfclistkg2.s

Cell co-ordinate: 1 , 6