

9A06 Component B48/14 (Right rear WSS (Weight Sensing System) sensor) has a short circuit to positive.

---

9A07 Component B48/14 (Right rear WSS (Weight Sensing System) sensor) has an open circuit in the wiring.

---

9A08 Component 'B48/13 (Left rear WSS (Weight Sensing System) sensor)' is defective.

---