

# Vehicle Diagnostic Report

---

## Car Information

Brand : BENZ

---

## Read codes

Fault Code	Status	Description
2078-002	Stored	Check component B28/8 (Pressure differential sensor (DPF)).The signal voltage is too low.
2084-002	MIL ON&Stored	Diesel particulate filter Flow monitoring of air massThe air mass is too small.
0105-008	Stored	Check component B5/1 (Charge pressure sensor).The atmospheric pressure between component B5/1 (Charge pressure sensor) and component N3/9 (CDI control unit) is implausible.
2355-001	MIL ON&Stored&Current	Check system 'Exhaust gas recirculation control'.The air mass is too small.