

1024MNRN 2 1024MNR	1024MNRN 2 1024MNR	1024MNRN 2 1024MNR	Frontier	Frontier	MB C250 Loaner	MB C250 Loaner	MB C250 Loaner	1024N2R
Improper install	Improper install			Manual shifts		Manual shifts		
3/8/2014	3/8/2014	3/9/2014	3/10/2014	3/10/2014	3/13/2014	3/13/2014	3/14/2014	
77.2	78.4	73.3	68.0	72.5	66.0	72.7	67.5	75.7
77.7	78.7	71.8	69.2	72.7	66.5	73.2	66.5	75.5

815N2R	815C N2R	815C N2R	815C N2R	815C N2R	915 CN	Frontier	915 CN	915 CN-10
							clamp offset not needed	
	3/24/2014	3/24/2014	3/25/2014	3/26/2014	3/30/14 1430	3/30/14 1430	3/31/14 1300	4/2/14 0030
75.2	71.5	71.8	73.7	70.3	71.9	65.5	71.8	75.2
77.2	72.6	72.7	73.8	69.9	73.0	65.0	71.7	75.9

915 CN-10	915 NE3	915 NE3	915 YNR 3N	915 4YNR	915 CN2R	915 CN2R	915 CN2R	915 CN2R	915 CN2R
	3" center 13/32 tension	wheel well insulation			1/4"	5/16"	3/8"	7/16"	13/32"
4/2/14 0100	4/2/14 1330	4/2/14 1530	4/3/14 1400	4/4/14 0030	4/4/14 1930	4/4/14 0030	4/4/14 0030	4/4/14 0030	4/4/14 0030
74.9	72.8	72.6	72.9	73.1	72.7	73.1	72.8	73.2	72.7
75.0	73.6	72.9	73.6	73.6	73.3	74.1	73.7	74.3	73.4

915B CN2R	915B CN2R	915B CN2R	915B CN2R	915B CN2R	1730 CSN4R2	1730 CSN4R2	Frontier	1730 CSN4R2
3/8"	3/8"	3/8"	3/8"	3/8"	3/8"	13/32"	NA	13/32"
4/8/14	4/9/14	4/10/14	4/10/14	4/10/14	4/11/14	4/11/14	4/11/14	4/12/14
0030	1645	0025	1630	2330	1230	2225	2300	1030
66.6	70.7	72.7	71.2	71.9	71.8	73.5	69.1	72.0
67.3	71.9	72.8	71.8	72.9	72.3	74.3	68.9	72.4