



This is the part that holds it together. I used a pair of needle nose pliers to pry these things apart. Managed to pry it open without breaking it. The part only cost \$5 at my local MB Dealer if it happens to break.

This is the plastic clamp that holds the Mass Air Flow Sensor on.