
Model 223

- 1 Rear center section paneling
- 2 Expansion rivet
- 3 Bracket
- 4 Trunk floor



P68.30-A074-76

Marning	Risk of injury caused by fingers being jammed or pinched when removing, installing or aligning hoods, doors, trunk lid/rear-end door or sliding roof.	No parts of the body or limbs should be within the operating area when the components are moving.	AS00.00-Z-0011-01A
	Notes on HANDS-FREE ACCESS		AH80.61-P-0001-01A
XX	Remove/install		
1	Open trunk lid.		
2	Lift trunk floor (4).		
3	Remove expansion rivets (2).	S Dismantling tool	*000589956300
4	Release holders (3) with a suitable tool and unclip with the special tool.	S Dismantling tool	*000589956300
5	Unclip rear-end center section cover (1) and remove upward.	S Long wedge	*115589035900
6	Install in the reverse order.		

