

## No Suspension Height Adjustment Possible. Production Mode Activated.

---

Topic number	LI32.22-P-074279
Version	2
Function group	32.22 - Air suspension
Date	8/2/22
Validity	Model 223, 297
Reason for change	Functionality: Deactivation of production mode possible using XENTRY.

---

### Complaint

Height adjustment and deactivation of the production mode not possible.

### Cause

The deactivation of the production mode is not stored in the AIRMATIC control unit. The control unit is not operational.

### Remedy

The production mode can be deactivated with XENTRY. If the deactivation is not to be saved, please update the software for the AIRMATIC control unit N51/8.

Symptoms				
Chassis/suspension > Suspension/Dampening > Suspension System Function > Vehicle level too high				
Chassis/suspension > Suspension/Dampening > Suspension System Function > Level does not react				
Chassis/suspension > Suspension/Dampening > AIRMATIC > Function > Vehicle is too high				

Control unit/fault code				
Control unit		Fault text		
N51/8 - AIRMATIC (Active suspension) (SPC223)		B15BF9A - Production mode is activated. The operating conditions for the component or the system are not satisfied.		
		B15BF00 - Production mode is activated. _		

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note