

All values measured to ground unless otherwise noted

Conn./Plug/Pin	Pin Information	Test Value	Comments
<u>K39</u>			
1	Circuit 15 main power input supplies horn relay solenoid high side and relay contact for horn function	12 VDC with ignition on	
2	Power output, supplies fanfare horns	12 VDC with fanfare horns activated	Feed from F1f11
3	Horn signal switched ground input to solenoid low side, activates relay K39	0 VDC with horn switch depressed 12 VDC with horn switch not depressed	Feed from S4/2
5	Circuit 15 main power input supplies horn relay solenoid high side	12 VDC with ignition on	
4, 6	pins not used		

