

# Operation items list

Work order for: 00 P.C.

Order number:

Date: 25.12.2013

Time: 20:08

Vehicle identification number: WDB 230 475 1F 008485

Family: 23 230 SL-Class

Model code: 21 SL 500

Sales designation: SL 500

Engine: 113 963

---

46-3900-06	4.3	Power steering pump Remove/install
32-7545-01	1.7	Valve block, front axle for Active Body Control (ABC) replace (after check)
32-7546-03	2.3	Valve block, rear axle for Active Body Control (ABC) replace (after check)
32-7498-01	0.6	Active Body Control (ABC) complete Bleed/vent
32-7501-01	1.2	Hydraulic fluid for Active Body Control (ABC) system Filter (after check)
32-7510-01	0.9	Oil reservoir for Active Body Control (ABC) replace
32-7518-02	1.0	Front axle pressure reservoir for Active Body Control (ABC) replace (after check)
32-7519-02	1.8	Rear axle pressure reservoir for Active Body Control (ABC) replace (after check)
32-7541-01	1.6	Valve unit, pressure supply for Active Body Control (ABC) replace (after check)
32-7543-01	1.2	Pressure sensor at the pressure supply valve unit for Active Body Control (ABC) Remove/install, seal
32-7544-01	1.0	Pressure sensor at the pressure supply valve unit for Active Body Control (ABC) replace (after check)
32-7561-01	1.5	Spring strut, front left for Active Body Control (ABC) replace
32-7562-01	1.5	Spring strut, front right for Active Body Control (ABC) replace
32-7563-01	2.2	Spring strut, (both) at front for Active Body Control (ABC) replace
32-7565-01	3.3	Spring strut, rear left for Active Body Control (ABC) replace
32-7566-01	3.3	Spring strut, rear right for Active Body Control (ABC) replace
32-7567-01	5.0	Spring strut, (both) at rear for Active Body Control (ABC) replace

---

17 Op. item      Total: 34.4 Hrs.