

Vehicle data

| | | | |
|-------------------------------------|------------------------|-----------------------------------|-------------------|
| Vehicle identification no. (FIN) | WDD 218391 1A 156055 1 | Order number | 0 5 706 87593 |
| Vehicle identification no. (VIN) | WDDLJ9BB5FA156055 | Production number | 7234215 7 |
| Brand | Mercedes-Benz | Body number | 2234496 |
| Category | PV (0) | Production plant | 0500 Sindelfingen |
| Vehicle model | CLS 550 4MATIC | Shipment date | 23.04.2015 |
| Body type | Coupe | Vehicle ownership title number | |

Major assemblies

| | | | |
|---|--------------------------|--|-------------|
| Engine no. | 278922 30 268973 | Engine object no. | A2780105703 |
| Transmission no. | 722967 06 292745 | Transmission object no. | 2122700709 |
| All-wheel drive transfer case number | | Transfer case object number | |
| All-wheel drive front axle transmission number | 22133076003012554202 | All-wheel drive front axle transmission object number | 2213307600 |
| Steering number | 218460 58 00021510004238 | Steering object number | 2184605800 |
| Frame-type integral support number | | Frame-type integral support object number | |
| Left front axle number | 2183300394001508602316 | | |
| Right front axle number | 2183300494001508602323 | | |
| Rear axle number | 21835003023843059000 | | |

Major assemblies - Adjustment dimension CVT transmission

| | |
|--------------|--------------|
| Pulley set 1 | Pulley set 2 |
|--------------|--------------|

Equipment

| | | |
|------------------------------------|-------------------------|---|
| Paintwork 1 | 183 U | MAGNETITE BLACK - METALLIC FINISH |
| Paintwork 2 | | |
| Interior equipment | 811 A | LEATHER/NAPPA/SEMI-ANILINE - BLACK/ANTHRACITE |
| Additional info interior equipment | 800 A | LEATHER/NAPPA/SEMI-ANILINE |
| Tire manufacturer | CONTINENTAL CONTINENTAL | |
| Lamps | | |
| Wind. wipers | | |
| Provisioning Certificate ID - PCID | | |

Infotainment

Radio unit number

CD changer device number

Sound-amplifier device number

Audio-video splitter device number

E-call device number DEEWA18257

Tele-Aid phone card (SIM)

Special equipment codes

| Code | Designation |
|------|--|
| 183U | MAGNETITE BLACK - METALLIC FINISH |
| 800A | LEATHER/NAPPA/SEMI-ANILINE |
| 811A | LEATHER/NAPPA/SEMI-ANILINE - BLACK/ANTHRACITE |
| 705L | UNITED STATES (USA) |
| 7XXL | NORTH AND SOUTH AMERICA |
| 055 | YOM 14/2 |
| 12B | OPERATORS MANUAL & SERVICE BOOKLET ENGLISH USA/CAN |
| 13A | OEL-OFFSETMENGE +1300ML OEL |
| 14U | SMARTPHONE INTEGRATION PACKAGE |
| 16U | SMARTPHONE INTEGRATION CARPLAY |
| 17U | SMARTPHONE INTEGRATION GOOGLE AUTOMOTIVE LINK |
| 1U2 | SNOW GRID |
| 232 | GARAGE DOOR OPENER WITH 284 - 390 MHZ FREQUENCY |
| 233 | AUTONOMOUS INT. CRUISE CONT. PLUS (DISTRONIC PLUS) |
| 235 | ACTIVE PARK ASSIST |
| 237 | ACTIVE BLIND SPOT ASSIST |
| 238 | ACTIVE LANE KEEPING ASSIST (FAP) |
| 23P | DRIVING PACKAGE |
| 249 | INSIDE AND OUTSIDE MIRROR AUTOMATIC DIMMING |
| 253 | REAR-END COLLISION WARNING AND PROTECTION SYSTEM |
| 264 | LICENSE PLATE ATTACHMENT AMERICA |
| 266 | DISTRONIC PLUS CROSS SUPPORT (DTR+Q) |
| 267 | MODEL PLATE DEVIATING |
| 268 | EXPANDED BRAKE ASSIST (BAS+) |
| 269 | BRAKE ASSIST PLUS CROSS TRAFFIC (BAS+Q) |

| | |
|------|--|
| 271 | AUTONOMOUS BRAKE INTERVENTION/WARN. FOR PED. PROT. |
| 275 | MEMORY PACKAGE (DRIVER SEAT, STRG. COL., MIRROR) |
| 287 | THROUGH-LOADING FEATURE |
| 291 | PELVIS AIRBAG (PELVISBAG) |
| 294 | KNEE AIRBAG |
| 300 | COLLISION MINIMIZATION BRAKE INTERV./WARNING (CMS) |
| 301 | ASHTRAY PACKAGE |
| 30A | DECKEL M. ZUS. UNTEREM TILGER-ANSCHRAUBPKT. |
| 342B | INSTRUMENT CLUSTER/HU LANGUAGE - AMERICAN |
| 348 | EMERGENCY CALL/SUPPORT SYSTEM |
| 35A | VGS D4-0, D3-MUSTER |
| 3U2 | HEAD UNIT AMERICA |
| 401 | FRONT SEAT CLIMATE CONTROL |
| 414 | ELECTRIC TILT/SLIDE SUNROOF IN GLASS VERSION |
| 427 | AUTOMATIC TRANSMISSION 7-SPEED |
| 432 | DYNAMICS SEAT,FRONT LEFT AND RIGHT |
| 443 | HEATED STEERING WHEEL |
| 461 | INSTRUMENT WITH MILES IND. AND ENGLISH LEGEND |
| 475 | TIRE PRESSURE MONITOR (TPM) HIGH LINE/MID LINE |
| 489 | AIRMATIC DUAL CONTROL / AIR SUSPENSION SEMI-ACTIVE |
| 494 | U.S. VERSION |
| 500 | OUTSIDE REAR VIEW MIRROR LH AND RH FOLDING |
| 501 | 360 DEGREE VIEWING SYSTEM (SURROUND VIEW) |
| 502 | 3 YEARS OF MAP UPDATES FREE OF CHARGE |
| 51U | BLACK FABRIC ROOF INTERIOR TRIM |
| 531 | COMAND APS NTG5/NTG5.5 |
| 536 | SIRIUS SATELLITE RADIO COMPLETE SYSTEM |
| 540 | ROLLER BLIND, ELECTRIC, FOR REAR WINDOW |
| 551 | ANTI-THEFT/ANTI-BREAK-IN WARNING SYSTEM |
| 580 | AIR CONDITIONER |
| 608 | AUTOMATIC HIGH BEAM SWITCH (IHC) |
| 60V | SPEED- + LOADINDEX 99H XL + 97H |
| 640 | DYNAMIC LED HEADLAMPS, SAE, RIGHT-HAND TRAFFIC |
| 690 | EMERGENCY SPARE TIRE (MINI SPARE) |
| 6P5 | STEUERCODE VERTRIEB FUER CODE 475 ANFORDERUNG |
| 731 | TRIM PIECES - WOOD BURRED WALNUT VENEER |
| 763 | RADIO REMOTE CONTROL W/ PANIC SWITCH (315 MHZ) |
| 772 | AMG STYLING PACKAGE-FRONT SPOILER, SIDE SKIRT |
| 790 | 18" AMG SPOKED WHEELS WITH MIXED TIRES |

| | |
|------|--|
| 805 | YOM 14/1 |
| 810 | PREMIUM SOUND SYSTEM |
| 815 | DVD SINGLE DRIVE |
| 820 | VEHICLES FOR TOURIST |
| 875 | HEATED SCREEN WASH SYSTEM |
| 877 | AMBIENCE ILLUMINATION |
| 881 | REMOTE TRUNK LOCKING |
| 887 | SEPARATE TRUNK LID LOCKING |
| 889 | KEYLESS - GO |
| 915 | FUEL TANK WITH GREATER CAPACITY - VOLUME 2 |
| 919 | AIRCON COOLING POWER PACKAGE |
| 950 | AMG SPORTS PACKAGE |
| 986 | DEVIATING VIN WITH MODEL YEAR |
| 989 | IDENTIFICATION LABEL UNDER WINDSHIELD |
| A20 | DIREKTSTART |
| A21 | SHIFT BY WIRE |
| A59 | FE-WANDLERGEH. 13,5 |
| A65 | FE-WANDLER 13,5MM |
| A68 | GETR.GEH. M.TIEFEN OELLEITUNGSANSCHLUSS |
| A89 | REIBUNGSREDUZIERT |
| A98 | NACHRUESTUNG GETRIEBESOFTWARE |
| B03 | DIRECT START / ECO START/STOP FUNCTION |
| B12 | WHEEL REPLACEMENT TOOL |
| F218 | SERIES PRODUCTION 218 |
| FC | COUPE |
| G967 | GETRIEBECODE AUSFUEHRUNG 67 |
| GA | AUTOMATIC TRANSMISSION |
| HA | REAR AXLE |
| J82 | --- |
| J8A | DSM STAR1 FBS4-REMOTESTART-FAEHIG |
| K15 | CONTROL CODE FOR SERVICE INTERVAL 15000 KM |
| L | LEFT-HAND STEERING |
| M005 | VEHICLES WITH 4-MATIC-/ALL WHEEL DRIVE |
| M278 | V8-GASOLINE ENGINE M278 |
| M46 | 4.6 LITER DISPLACEMENT |
| N5A | STEUERCODE W50 FUER PPS-INT. VERWENDUNG |
| P17 | KEYLESS-GO PACKAGE |
| P44 | PARKING PACKAGE |
| P49 | MIRRORS PACKAGE |

VeDoc

| | |
|-----|--|
| R02 | ALL SEASON TYRES |
| U10 | FRONT PASSENGER SEAT WITH WEIGHT SENSING |
| U12 | FLOOR MATS - VELOUR |
| U71 | DVD PLAYER WITH REGIONAL CODE 1, USA |
| VL | FRONT AXLE HALF, LEFT |
| VR | FRONT AXLE HALF, RIGHT |

VPD data

| VPD ident | Designation | Content |
|-----------|---|---|
| 00013 | Fuel Tank | 21247047011511110342 |
| 00048 | MEID Mobile Equipment Identifier | A1000005CEF3C4 |
| 00049 | MDN Mobile Directory Number | 6148359042 |
| 00050 | MIN Mobile Identification Number | 6142537565 |
| 10199 | Wheel Electronic Identifier | 04330000C0FA570000C1363B0000C0605E0000C |
| 10200 | Injector Quantity Adjustment 1 | 322D |
| 10201 | Injector Quantity Adjustment 2 | 312D |
| 10202 | Injector Quantity Adjustment 3 | 312F |
| 10203 | Injector Quantity Adjustment 4 | 302D |
| 10204 | Injector Quantity Adjustment 5 | 312D |
| 10205 | Injector Quantity Adjustment 6 | 302C |
| 10206 | Injector Quantity Adjustment 7 | 322C |
| 10207 | Injector Quantity Adjustment 8 | 2E28 |
| 10225 | SSG Driver Normalizing Position | 3C5D;37FC;3BB3;38F7;39FB;FFFF;3BC9;3B22 |
| 10226 | SSG Driver Reference Position | 3C5D;37FC;3BB3;38F7;39FB;FFFF;3BC9;3B22 |
| 10228 | SSG Passenger Normalizing Position | 3C82;3801;3BBB;3904;39FC;FFFF;FFFF;FFFF |
| 10229 | SSG Passenger Reference Position | 3C82;3801;3BBB;3904;39FC;FFFF;FFFF;FFFF |
| 20002 | EGS Code | w43ba06p12stvvyfap12 |
| 30021 | SCN EZS (Electronic Ignition Switch Module) | 2189054701010003 |
| 30043 | SCN LRSM (Light Rain Sensor) | 2049014504010016 |
| 30044 | SCN WSS (Windscreen) | 2186701300010001 |
| 30125 | SCN OCM (Occupant Classification Module) | 2078700410010002 |

Serial numbers

| Designation | Serial number | Object number | From VPD ID |
|------------------------------|------------------------|---------------|-------------|
| Starter Battery | 0009822108133510507292 | 0009822108 | 00030 |
| EZS Configuration Value FBS4 | 0E00 | | 00054 |

| | | | |
|---|--|------------|-------|
| Airbag Sensor Sidebag feft | 0C553036 | 0C553036 | 10003 |
| Airbag Sensor Sidebag right | 371D2736 | 371D2736 | 10004 |
| Airbag Unit Driver | 0008604000911670150920021X | 0008604000 | 10006 |
| Airbag Unit Front Passenger | 2188600602111510300506 | 2188600602 | 10007 |
| Sidebag Unit front left | 2128603402211510306179 | 2128603402 | 10008 |
| Sidebag Unit front right | 2128603502201510403992 | 2128603502 | 10009 |
| Airbag Pressure Sensor front left | 306B4806 | 306B4806 | 10014 |
| Airbag Pressure Sensor front right | 3B6C4806 | 3B6C4806 | 10015 |
| Gearbox Control Unit | 00090171009E1508100147 | 0009017100 | 10019 |
| Pelvic Airbag Unit left | 2128602302211509914390 | 2128602302 | 10023 |
| Pelvic Airbag Unit right | 2128602402201509905406 | 2128602402 | 10024 |
| Airbag Seam/Weakening Front Passenger | 21868057879G81301510719871 | 2186805787 | 10036 |
| Brake Unit | 2124301330221509703349 | 2124301330 | 10037 |
| Windowbag Unit left | 2188600102171509000330 | 2188600102 | 10050 |
| Windowbag Unit right | 2188600202171509000784 | 2188600202 | 10051 |
| Damper and Damper Tube front left | 2123203338021509753056 | | 10072 |
| Damper and Damper Tube front right | 2123203438021508601453 | | 10073 |
| Occupant Classification Passenger Airbag | 28359826;A;A207;Q2;2078700410 ;N;R;057203506 | 28359826;A | 10089 |
| Kneebag Unit left | 2128600902111509801835 | 2128600902 | 10090 |
| Airbag Sensor Upfront left | 5B163D36 | 5B163D36 | 10104 |
| Airbag Sensor Upfront right | 64083D36 | 64083D36 | 10105 |
| Kneebag Unit right | 2188600302111509900642 | 2188600302 | 10107 |
| Control Unit reversible Belt Tensioner front left | 2049016803 15040721001200FFFFFF | 2049016803 | 10122 |
| Control Unit reversible Belt Tensioner front right | 2049016903 15032721000392FFFFFF | 2049016903 | 10123 |
| Sensor Cluster 1 Brake Control System | 0009059101181504020042435560 | 0009059101 | 10164 |
| Battery Sensoring | 0F55C5BB0B | 0F55C5BB0B | 10167 |
| SDARS Serial Number 1 | 067068992355 | | 10171 |
| Gearbox Control Unit (FBS4 Serial Number) | 600001553748103213012301 | | 10214 |
| Catalyst 1 | 2184901219101511017899 | 2184901219 | 10251 |
| Catalyst 2 | 2184901119101511017883 | 2184901119 | 10252 |
| DSM Direct Select Module (FBS4 Serial Number) | 700001510686403213012301 | | 10291 |
| Engine Control Unit (FBS4 Serial Number) | 600001618316601013012301 | | 10293 |
| EZS Electronic Ignition Starter Lock (FBS4 Serial Number) | 300001484954401412012201 | | 10294 |

FO texts

| DG | Text content | Author | Date |
|----|---|--------|------------------|
| 82 | SA code 14U added as per WIS doc# AZ82.60-P-0028NKM | BPIRES | 05.10.2018 15:48 |

Control units

| Short des. | Designation | Version | Hardware object number | Installation date |
|------------|--|---------|------------------------|-------------------|
| SFD | SEAT-D Sitzsteuergerät Fahrer | | 172 901 88 01 | |
| SFP | SEAT-P Sitzsteuergerät Beifahrer | | 172 901 89 01 | |
| SND | SND Soundverstärker | | 218 901 76 00 | |
| ORC | ORC Airbag-Steuergerät | | 212 901 11 05 | |
| KG | KG Keyless-Go | | 212 901 01 07 | |
| EPS | EPS Steuergerät elektrische Lenkung | | 204 901 01 04 | |
| TVSDAR | TV TV-Tuner vorne | | 222 901 50 04 | |
| SMPC | MPC Multi Purpose Camera | | 207 901 41 00 | |
| SPC | SPC Advanced-Agility-Steuergerät | | 212 901 01 00 | |
| ARS | DTR DISTRONIC Steuergerät | | 000 901 91 02 | |
| TS2 | TSG-VR Türsteuergerät vorne rechts | | 212 901 17 05 | |
| GSL | GSL Gurtstraffer links | | 204 901 68 03 | |
| TDS | TDS Tank-Steuergerät | | 000 901 21 00 | |
| TS3 | TSG-HL Türsteuergerät hinten links | | 218 820 15 26 | |
| RDA | RDA TeleAid Remote Diagnostics Application | | 172 901 94 02 | |
| SMH | SAM-H SAM-Modul hinten | 21 | 212 901 53 05 | |
| PXLL | PXL-L Pixel-Steuergerät links | | 218 901 45 01 | |
| PTS | PTS Parktronic-System | | 000 901 76 02 | |
| LRR | LWR-S Leuchtweitenregulierung Slave | | 218 901 21 01 | |
| LRL | LWR-M Leuchtweitenregulierung Master | | 218 901 21 01 | |
| MRM | SCM Mantelrohrschaftmodul | | 212 901 79 03 | |
| ESP | ESP Elektronisches Stabilitätsprogramm | | 212 901 88 04 | |
| MMSF2 | RDU-S2 RDU-Sensor 2 | | 000 905 67 00 | |
| PTCM | ARWT Automatische Rückwandtür | | 212 820 04 26 | |
| PASS | LCT Low Cost TeleAid | | 253 901 23 00 | |
| ZBE | ZBE Zentrale Bedieneinheit | | 212 901 90 08 | |
| MMSR1 | RDU-S5 RDU-Sensor 5 | | 000 905 67 00 | |
| KI | KI Kombiinstrument | | 218 901 60 00 | |
| SVS | SVS Surround View System | | 207 901 40 00 | |
| SAM | SAM-V SAM-Modul vorn | 3 | 212 901 46 07 | |
| MMSR4 | RDU-S8 RDU-Sensor 8 | | 000 905 67 00 | |
| VRDU | RDU Radar-Steuergerät | | 099 901 21 00 | |
| MMSR2 | RDU-S6 RDU-Sensor 6 | | 000 901 79 01 | |
| TPM | RDK Reifendruckkontrolle | | 000 901 78 03 | |
| PXLR | PXL-R Pixel-Steuergerät rechts | | 218 901 45 01 | |
| GSR | GSR Gurtstraffer rechts | | 204 901 69 03 | |

| | | |
|-------|-------------------------------------|---------------|
| DBE | DBE operating panel roof | 212 901 38 06 |
| TS4 | TSG-HR Türsteuergerät hinten rechts | 218 820 16 26 |
| ZGW | ZGW Zentrales Gateway | 231 901 31 02 |
| PFD | PFD Pumpe Fahrdynamischer Sitz | 000 800 57 48 |
| DSM | ISM Intelligentes Servomodul | 005 446 19 10 |
| KLA | KLA-V Klimabedieneinheit vorne | 204 901 69 04 |
| MSG | MSG Motor-Steuergerät | 278 901 13 00 |
| HU | HU Head Unit | 218 901 30 01 |
| ZDP | ZDP Zentraldisplay | 218 901 32 01 |
| FDSL | MKS-VL Multikontursitz vorne links | 212 820 65 26 |
| NAG | GSG Getriebe-Steuergerät | 000 901 71 00 |
| IGW | IGW Inselgateway | 212 901 02 03 |
| TS1 | TSG-VL Türsteuergerät vorne links | 212 901 16 05 |
| MMSF3 | RDU-S3 RDU-Sensor 3 | 000 905 67 00 |

History

| Date | User ID | Tab | Attribute name | Old value | New value |
|------------|----------|---------------|--|------------------|--------------------------|
| 29.03.2019 | D7NALOVO | Control units | Software object number | 2789039600 | |
| 29.03.2019 | D7NALOVO | Control units | Software object number | 2789023300 | |
| 29.03.2019 | D7NALOVO | Control units | Software object number | | 2789032401 |
| 29.03.2019 | D7NALOVO | Control units | Software object number | | 2789023600 |
| 29.03.2019 | D7NALOVO | Control units | Serial number | | 600001618316601013012301 |
| 29.03.2019 | D7NALOVO | Control units | Date of the first access by the field organization | | 29.03.2019 |
| 29.03.2019 | D7NALOVO | Control units | CVN | B9682708 | AED9097B |
| 29.03.2019 | D7NALOVO | Control units | Date of the first access by the field organization | | 29.03.2019 |
| 29.03.2019 | D7NALOVO | Control units | Software object number | 0009025912 | |
| 29.03.2019 | D7NALOVO | Control units | Software object number | | 0009024925 |
| 28.03.2019 | D7NALOVO | Control units | Software object number | 1769024802 | |
| 28.03.2019 | D7NALOVO | Control units | Software object number | | 1769027702 |
| 28.03.2019 | D7NALOVO | Control units | Date of the first access by the field organization | | 28.03.2019 |
| 28.03.2019 | D7NALOVO | Control units | Date of the first access by the field organization | | 28.03.2019 |
| 28.03.2019 | D7NALOVO | Control units | Date of the first access by the field organization | | 28.03.2019 |
| 28.03.2019 | D7NALOVO | Control units | Version | | 21 |
| 28.03.2019 | D7NALOVO | Control units | Date of the first access by the field organization | | 28.03.2019 |
| 28.03.2019 | D7NALOVO | Control units | Date of the first access by the field organization | | 28.03.2019 |
| 28.03.2019 | D7NALOVO | Control units | Software object number | 2129020609 | |
| 28.03.2019 | D7NALOVO | Control units | Software object number | | 2129025711 |
| 28.03.2019 | D7NALOVO | Control units | Version | | 3 |
| 28.03.2019 | D7NALOVO | Control units | Control unit model | | VPDPAR |
| 11.10.2018 | d7mspald | Control units | Software calibration number | 1769024802150041 | 1769024802150889 |
| 11.10.2018 | SDAYKIN | Codes | Special equipment code number | | 17U |

VeDoc

Status Delivered

| | | | | | |
|------------|---------|--------------------------------------|--|------------------|---|
| 11.10.2018 | SDAYKIN | Codes | Special equipment code number | | 16U |
| 05.10.2018 | BPIRES | FO texts | Text content | | SA code 14U added as per WIS doc# AZ82.60-P-0028NK... |
| 05.10.2018 | BPIRES | Codes | Special equipment code number | | 14U |
| 20.02.2018 | d7***** | License data | Development status | | **** |
| 20.02.2018 | d7***** | License data | Development status | | **** |
| 20.02.2018 | d7***** | License data | Navigation compatibility identifier | 43 | 00 |
| 20.02.2018 | d7***** | Control units / Additional component | Meaning | Component | |
| 20.02.2018 | d7***** | Control units | Theft protection PIN | **** | **** |
| 20.02.2018 | d7***** | Control units | Serial number | MEB530F216C046 | MEG340H4052036 |
| 20.02.2018 | d7***** | Control units | Theft protection PIN | **** | **** |
| 19.09.2017 | D7***** | Control units | Software object number | 2129023711 | |
| 19.09.2017 | D7***** | Control units | Software object number | 2129021711 | |
| 19.09.2017 | D7***** | Control units | Software object number | | 2129026011 |
| 19.09.2017 | D7***** | Control units | Software object number | | 1769024802 |
| 19.09.2017 | D7***** | Control units | Software calibration number | 2129023711010134 | 1769024802150041 |
| 19.09.2017 | D7***** | Control units | Date of the first access by the field organization | | 19.09.2017 |
| 19.09.2017 | D7***** | Control units | Software object number | 2189040600 | |
| 19.09.2017 | D7***** | Control units | Software object number | 2189033300 | |
| 19.09.2017 | D7***** | Control units | Software object number | 2189023604 | |
| 19.09.2017 | D7***** | Control units | Software object number | | 2189033800 |
| 19.09.2017 | D7***** | Control units | Software object number | | 2189025605 |
| 19.09.2017 | D7***** | Control units | Software object number | | 2189040800 |
| 19.09.2017 | D7***** | Control units | Date of the first access by the field organization | | 19.09.2017 |
| 19.09.2017 | D7***** | Control units / Additional component | Identification/serial number | | 067068992355 |
| 19.09.2017 | D7***** | Control units | Software object number | 2229027010 | |
| 19.09.2017 | D7***** | Control units | Software object number | 2229026910 | |
| 19.09.2017 | D7***** | Control units | Software object number | | 2229021014 |
| 19.09.2017 | D7***** | Control units | Software object number | | 2229043101 |
| 19.09.2017 | D7***** | Control units | Software calibration number | 2229027010010005 | 2229021014150006 |
| 19.09.2017 | D7***** | Control units | Serial number | | DL4300F0500361 |
| 19.09.2017 | D7***** | Control units | Date of the first access by the field organization | | 19.09.2017 |
| 19.09.2017 | D7***** | License data | Navigation compatibility identifier | 00 | 43 |
| 19.09.2017 | D7***** | Control units | Date of the first access by the field organization | | 19.09.2017 |
| 19.09.2017 | D7***** | Control units | Software object number | 2129028210 | |
| 19.09.2017 | D7***** | Control units | Software object number | | 2129025511 |
| 19.09.2017 | D7***** | Control units | Software calibration number | 2129028210010004 | 2129025511150005 |
| 01.07.2015 | d2***** | Sales data | Initial registration date | | 30.06.2015 |

VIN: WDD LJ9B [REDACTED]

Current advice for the vehicle:
none

Outstanding KDM:

| Damage code | Description | End date | Campaign state | KDM-Type | Days to Expire |
|-------------|---|----------|----------------|------------------|----------------|
| 4694011 | Campaign 2019080019 - Replace Steering Gear Bolts | | Active | Service-Campaign | 0 |

ESKULAB decisions:

Damage history:

| Type | Rep. Date | X | # | Damage code | Damage code description | Claim No. | L-RZ | Area | LL | M | EC | Credit note no. | Credit note date |
|------|------------|----|----|-------------|--|-----------|------|-------|-------|-----|----|-----------------|------------------|
| | 07.11.2019 | | 16 | 091A37177 | Cushion frame, seat, front, left Too much play | 529218 | USA | 30104 | 55899 | mls | 1 | 000006819 | 26.11.2019 |
| | 07.11.2019 | | 15 | 042301D67 | Actuator, parking brake Stiff/sluggish | 529218 | USA | 30104 | 55899 | mls | 1 | 000006819 | 26.11.2019 |
| | 01.04.2019 | | 14 | 08209Z908 | Communications module, telematics service Software status | 155934 | USA | 80201 | 46127 | mls | 1 | 000006652 | 05.04.2019 |
| | 27.03.2019 | | 13 | 054575908 | Control unit, gasoline engine Software status | 155490 | USA | 80201 | 46097 | mls | 1 | 000006650 | 03.04.2019 |
| | 27.03.2019 | | 12 | 054001737 | Battery Electrical fault | 155490 | USA | 80201 | 46097 | mls | 1 | 000006650 | 03.04.2019 |
| | 03.05.2018 | AA | 11 | 054027737 | Buffer battery Electrical fault | 112627 | USA | 51195 | 39358 | mls | 1 | 000006418 | 11.05.2018 |
| | 15.02.2018 | | 10 | 087100E67 | Head unit Total failure | 107926 | USA | 51195 | 33274 | mls | 1 | 000006364 | 24.02.2018 |
| | 19.09.2017 | AA | 9 | 054027737 | Buffer battery Electrical fault | 99919 | USA | 51195 | 28666 | mls | 1 | 000006255 | 26.09.2017 |
| | 19.09.2017 | | 8 | 082190908 | KEYLESS control unit, interior Software status | 99919 | USA | 51195 | 28666 | mls | 1 | 000006255 | 26.09.2017 |
| | 19.09.2017 | | 7 | 08231V508 | Function, media player (USB/SD/CD), head unit Shows incorrect readings | 99919 | USA | 51195 | 28666 | mls | 1 | 000006255 | 26.09.2017 |
| | 29.08.2017 | | 6 | 088201428 | Engine hood Poor fit | 98607 | USA | 51195 | 27950 | mls | 1 | 000006238 | 01.09.2017 |
| | 16.01.2017 | | 5 | 021776007 | ??? Special regulation | 85099 | USA | 51195 | 19961 | mls | 1 | 000006079 | 21.01.2017 |
| | 16.01.2017 | | 4 | 081N11D68 | Sun visor right Stiff/sluggish | 85099 | USA | 51195 | 19961 | mls | 1 | 000006076 | 18.01.2017 |
| | 14.05.2016 | | 3 | 021775007 | ??? Special regulation | 70165 | USA | 51195 | 10114 | mls | 1 | 000005901 | 17.05.2016 |

VIN: WDD LJ9BB5 [REDACTED]

KDM-History:

| Rep. Date | Damage code | Damage code description | End date | Campaign state | Claim No. | L-KZ | Area | LL | M |
|-----------|-------------|---|----------|----------------|-----------|------|------|----|---|
| | 4694011 | Campaign 2019080019 - Replace Steering Gear Bolts | | Active | | | | 0 | |