


MODEL 231



P88.10-2270-08

1 Rear fender liner section
2 Nut

3 Expansion clip
4 Screw

5 Front fender liner section

☒ ☒	Remove/install		
⚠ Danger !	Risk of death caused by vehicle slipping or toppling off of the lifting platform.	Align vehicle between vehicle lift columns and position the four support plates at the vehicle lift support points specified by vehicle manufacturer.	AS00.00-Z-0010-01A
1	Lift vehicle on vehicle lift		AR00.60-P-1000TX
2	Remove expansion clips (3)	i Installation: Replace damaged expansion clips (3).	
3	Remove bolts (4)		
4	Unscrew nuts (2) from rear fender liner section (1)		
5	Remove rear fender liner section (1)		
6	Unscrew nuts (2) from front fender liner section (5)		
7	Remove front fender liner section (5)		
8	Install in the reverse order		