LINE OPCODE TECH TYPE HOURS		LIST	NET	TOTAL					
A CUSTOMER STATES NOISE IN FRONT SUSPENSIONCREEKINGCV 029560 DIAGNOSTIC TESTING - NO TROUBLE FOUND,									
PERFORM	- NO TROUBLE FOUND,								
5 W40				/NI /CI)					
				(N/C)					
- War (1997)									
8521 VERIFIED FRONT SUSPENSION NOISE. WAS ABLE TO HEAR NOISE WHEN TURNING STEERING WHEEL RIGHT OR LEFT. PREFORM UNDERBODY CHASSIS NOISE INSPECTION. FOUND LEFT TORQUE STRUT ARM AND LEFT LOWER CONTROL ARM HAVE ALIGNMENT BOLTS INSTALLED. THE LOWER CONTROL ARM BOLT IS NOT INSTALLED PROPERLY. WOULD RECOMMEND HAVING ALIGNMENT PREFORMED. ALSO FOUND RIGHT LOWER CONTROL ARM BOLT LOOSE WHICH IS CASUING CREEKING NOISE. TIGHTEN BOLT AND REDROVE. CHECK OK AT THIS TIME.									

B CUSTOMER STATES DELAY/HESITATION ON HARD ACCELERATIONCV 541011 SHORT TEST, PERFORM									
5 W40				(N/C)					
540991 CONTROL UNIT - SOFT	WARE (AFTER SHORT								
TEST), INSTALL				((-)					
5 W40 540992 CONTROL UNIT CODE (AFTER SHORT TEST), PERFORM				(N/C)					
5 W40				(N/C)					
8521 TEST DROVE TO VERIFY COMPLAINT. WHEN CAR IS AT COMPLETE STOP, A HESITATION IS FELT ON HARD ACCELERATION. PREFORM SDS TEST. NO CODE OR EVENTS IN ANY CONTROL MODULE. CHECK FOR UPDATED SOFTWARE. INSTALL MESFI SOFTWARE. CODE MESFI. INSTALL ETC SOFTWARE. CODE ETC. REDROVE AFTER									
					REPAIR. FOUND COMPLAINT TO ONLY HAPPEN IN SPORT MODE AND NOT COMFORT				
					MODE. SPORT MODE WILL BE MORE FIRM ON ACCELERATION.				
*********	********	*****	***************************************						
C OIL AND FILTER CHANGE (VALUE PRICING)									
3 OIL AND FILTER CHANGE (V			oo 00000000000000000000000000000000000						
LIMITED WARRANTY: The only warranties applying to the part(s) installed in accordance with this estimate are those	reason or non-payment or other reason and placed in the hands of an attorney, I agree to pay all reasonable attorney fees , court costs and expenses incurred in the handling and/or collection of the balance. Any balance, 30 days or more past due and	DESCRIPTION LABOR AMOUNT		TOTALS					
that may be offered by the manufacturer. The seller, MERCEDES-BENZ OF MEMPHIS, hereby expressly disclaims		PARTS AMOUNT							
all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of products or service sold under the terms of this estimate. MERCEDES-BENZ OF MEMPHIS, does not guarantee that the work performed in accordance with this estimate will correct a problem specified on the description of the complaint. Repair work done on this order will be based in part on a flat rate manual computation.		2.2 20 202							
		SUBLET AMOUNT							
		MISC. CHARGES							
		TOTAL CHARGES							
		LESS INSURANCE							
		SALES TAX							
		PLEASE PAY THIS AMOUNT							
		THE AMOUNT							