

01/2010 [2009.12.03] - AddOns: 1361,1383,1380,1390,1394,1396,1400,1407,1411,1418,1416,1427,1426,1434 VIN: WDDDJ76X16AL66150 Battery voltage: 12.1 V

Vehicle **219.376** Control unit

Current quick test:

Filter status: All control units

MB number	HW version	SW version	Diagnosis version	Pin
1131530591	04 2005	29 2005	6/187	7

Code	Text	Status
P2094-002	Actual value potentiometer 2 of throttle valve - Short circuit to ground or open circuit	STORED
P202E-008	M16/6 (Throttle valve actuator) : Deflection of throttle valve (P0120)	STORED
P2093-001	Actual value potentiometer 1 of throttle valve - Short circuit to battery or reference voltage	STORED
P2006-002	B17/8 (Charge air temperature sensor) : Short circuit to positive or open circuit (P0112)	STORED
P202B-002	Idle speed control implausible : Short circuit to ground or open circuit	STORED
P207E-001	The efficiency of the left catalytic converter is insufficient (function chain) (P0432)	Current and stored
P20A2	Idle speed control implausible : Check system for unmetered air.	Current and stored
P2007-008	B28 (Pressure sensor) : Signal implausible	STORED
P2007-008	B28 (Pressure sensor) : Signal implausible	STORED
P200B-001	The efficiency of the right catalytic converter is insufficient (function chain) (P0422)	Current and stored

ETC - Electronic transmission control

ESC F3 F8 F11