

Service History:

- A. May, 2017, @101,384 Miles – Performed A Service
- B. March 2017, @ 98,795 miles – Front left lower Control arm bushing replaced under Warranty
- C. January 2017, @ 92,578 Miles – Right Turbo Charger replaced under Warranty
- D. December 2016, @ 90,000 Miles – New rotors and pads, along with rear Differential fluid service, Transmission Fluid, Air Filter, Brake Fluid service, Engine filters, oil service
- E. September 2016, @ 80,541 – B Service, New Dust Filter, Brake Flush
- F. May 2016, @ 70,552 Miles – Strut Noise fixed under Warranty by, Left & Right Spring Cups Lubrication per LI32-25-P-051645. Also Performed 70,000 mile service
- G. February 2016, @80,000 Miles – Performed 60,000 Mile service
- H. January 2016, @ 57, 422 Miles – Rattles and squeaks repaired under Warranty; Overhead Control panel, and Panorama Bolts tightened
- I. October 2015, @ 50,619 Miles – Overhead Center Control Rattle adjusted/fixed under Warranty. Also performed 50,000 Mile Service.
- J. July 2015, @ 40,197 Miles - \$40,000 mile service, Cabin Filter and wiper blades replaced, Transmission fluid and filter replaced, along with Rear Differential Service, Engine Filters
- K. April 2015, @ 30,784 Miles – 30,000 mile service. Balanced all four wheels
- L. February 2015, @25,551 Miles – Slight rattle from Overhead Console fixed under Warranty by removing headliner and installing insulation between headliner clips and Roof panel.
- M. December, 2014 @ 21,418 Miles – Front & rear Brake Pads & Rotors replaced under Warranty. Also performed 20,000 mile service.
- N. September, 2014 @ 10,937 Miles – Updated Transmission Control Module Software Recall Campaign # 2014050002. Performed 10,000 Service
- O. April 2014, @2,805 Miles – Changed Rear Differential Fluid. Realigned front bumper with hood to eliminate wind noise, as well adjust front left seat height to eliminate noise from adjuster.

Description & Options (February 26, 2014 In-Service Date):

Code	Description	MSRP
	E63P	\$99,770
755	Steel Grey	
821	Black Nappa Leather with Cont. Stich/Silver	
P60	AMG Exterior Night Styling	\$750
U70	Red Brake Calipers	
Y04	Safety Belts in Silver	
068	Wheel Locking Nuts	\$140
076	Factory Code	
137	Comfort Box	\$290
413	Power Tilt / Sliding Panorama Sunroof	\$1,090
736	Black Ash Wood Trim	
797	19-Inch AMG 10-Spoke Wheels - Silver	
8U1	Factory Code	
810	Harman /Kardon LOGIC7 Surround Sound System	
993	Lane Tracking Package: Blind Spot Assist	\$875
995	AMG Parking Assist Package: Surround View	\$800
	Destination & Delivery	\$925
	TOTAL	\$104,640