

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

REPLACE FRONT BRAKE PADS

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2018080016, September 2018

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Replace Front Brake Pads
Model AMG E63 S (213 platform)
Model Year 2018

Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY18 E-Class (213 platform) vehicles, the front brake pads may not meet production specifications, which could result in excess brake noise, and/or brake pad wear. An authorized Mercedes-Benz dealer will replace the front brake pads for the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 4 vehicles are affected.


Order No. P-SC-2018080016

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

 Model 213 with code U70 corresponds to: BRAKE CALIPERS PAINTED RED

Procedure

1. Replace brake pads of front axle on left and right.
 For basic data see **AR42.10-P-1610LWD**.


Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
1	Brake pad parts kit for model 213	A 000 420 91 00	100%

Warranty Information

Operation: Replace brake pads of front axle (02-2420)
Includes: Remove/install 2 wheel and tire assemblies; Perform brake test run

Damage Code	Operation Number	Labor Time (hrs.)
42 960 35 7	02-2420	1.3

 **Note**
Operation Number labor times are subject to change.