

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle &gt; Technical Service Bulletins

## AMG PERFORMANCE STEERING WHEEL HEAVILY SOILED/WORN



## - AMG Performance Steering Wheel Heavily Soiled/Worn -

Topic number	LI46.10-P-055432
Version	11
Function group	46.10 Steering wheel, jacket tube, steering shaft, steering lock
Date	09-22-2020
Validity	All vehicles with code 281 and L6* (AMG Performance steering wheel with Dinamica microfiber or Alcantara)
Reason for change	Validity extended

### Complaint

Soiling/wear on the AMG Performance steering wheel with Dinamica microfiber or Alcantara.

**File**

IMG\_0121\_Lenkrad.JPG.jpg

**Designation**

Steering wheel soiled (left) and cleaned (right)

### Cause

Soiling from e.g. dust, grease, sweat etc.

### Remedy

See owner's manual, "Care of the interior":

- Clean the steering wheel with a 1% soap solution, e.g. washing-up liquid, and a damp cloth.
- Clean all parts of the covering in order to avoid edges.
- Then let the steering wheel dry.
- The cleaning results depend on the nature and age of the soiling.

Note: the costs must not be invoiced through the warranty.

### Symptoms

**Symptom**

Chassis/suspension / Steering system / Steering wheel / Surface damage

IMG\_0121\_Lenkrad

