

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

## WINTER TIRE SPEED LIMIT IS ACTIVATED AUTOMATICALLY



Mercedes-Benz

# - Winter tire speed limit is activated automatically -

Topic number	LI54.30-P-068427
Version	1
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	07-20-2018
Validity	E63 AMG BR 213
Reason for change	

## Complaint

---

Display in instrument cluster at 235 km/h (146mph) "Speed limit (winter tires) 240 km/h"

Speed is limited to 240 km/h (146 mph)

## Cause

---

Lack of communication between ESP control unit and COMAND at system start.

## Remedy

---

Updating of ESP control unit and COMAND control unit with XENTRY (version 05/2018 or higher)

Note:

Only one control unit may also be affected by the update.

## Symptoms

---

### Symptom

Communication/information / Assistance and warning systems / DISTRONIC / Display message / Function error

Communication/information / Assistance and warning systems / DISTRONIC / Function / Implausible regulation

Communication/information / Assistance and warning systems / Speed Limit Assist / Warning message in instrument cluster