


ELECTRICAL SYSTEM - ENGINE -- 203 CHASSIS			
aps	Fig. 86: Identifying Crankshaft Position Sensor Remove/Install Components - Engine 272.920/940/941 2006 Mercedes-Benz C230		
			
1 Bolt	B70 Crankshaft Hall sensor	P07 04251508	
Tuesday, November 23, 2010 12:22AM		Page 1	© 2005 Mitchell Repair Information Company, LLC.