

FIN: WDD 204001 2R 277502

Current advice for the vehicle:

none

















Outstanding KDM:




none

ESKULAB decisions:

none

Damage history:

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	24.05.2016	AA	19	000012SV7	Minor service scope/Service A Service contract	8571308	SA	00100	44955	km	0	000000000	
	24.05.2016	AB	18	08209USV7	Wiper blade, front (service contract) Service contract	8571308	SA	00100	44955	km	0	000000000	
	24.05.2016	AC	17	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	8571308	SA	00100	44955	km	0	000000000	
	06.04.2016		16	080602737	Transmitter key, infrared/radio remote control Electrical fault	8568853	SA	00100	44937	km	1	000001946	14.05.2016
	10.02.2016	AD	15	042101D17	Brake disc, front Worn	8565633	SA	00100	38471	km	1	000001888	24.02.2016
	10.02.2016		14	04230HD17	Brake lining, front, rear Worn	8565633	SA	00100	38471	km	1	000001888	24.02.2016
	10.02.2016		13	05406W737	Relay, wiper park position heater Electrical fault	8565633	SA	00100	38471	km	1	000001888	24.02.2016
	23.07.2015		12	020001047	Coolant pump Leaks	0661710	SA	00193	38471	km	1	000001737	25.07.2015
	25.05.2015		11	000011SV7	Major service scope/Service B Service contract	0660543	SA	00193	35270	km	1	000001696	29.05.2015
	25.05.2015		10	040221208	Wheel, disk wheel, light alloy with tires Unbalance	0660543	SA	00193	35270	km	1	000001696	29.05.2015
	25.05.2015		9	043000SV7	Brake fluid change Service contract	0660543	SA	00193	35270	km	1	000001696	29.05.2015
	25.05.2015	AB	8	08209USV7	Wiper blade, front (service contract) Service contract	0660543	SA	00193	35270	km	1	000001696	29.05.2015
	25.05.2015	AC	7	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	0660543	SA	00193	35270	km	1	000001696	29.05.2015
	12.05.2014	AA	6	000012SV7	Minor service scope/Service A Service contract	0653642	SA	00193	20054	km	1	000001429	15.05.2014
	12.05.2014	AD	5	042101D17	Brake disc, front Worn	0653642	SA	00193	20054	km	1	000001429	15.05.2014
	12.05.2014		4	042114D17	Brake lining, front Worn	0653642	SA	00193	20054	km	1	000001429	15.05.2014

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	12.05.2014		3	042214D17	Brake lining, rear Worn	0653642	SA	00193	20054	km	1	000001429	15.05.2014
	12.05.2014	AC	2	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	0653642	SA	00193	20054	km	1	000001429	15.05.2014
	12.05.2014		1	021944SK8	QR Code Adhesive Label	0653643	SA	00193	20054	km	3	000001429	15.05.2014