
Clearcoat peeling / flaking / bubbling

Topic number	LI98.00-P-058914
Version	2
Design group	98.00 General
Date	06-12-2014
Validity	All vehicles with 590 - Mars Red only
Reason for change	Damage code updated

Complaint:

Exterior clearcoat finish is peeling, flaking, or exhibits bubbles under the surface

Attachments	
File	Description
Peeling clearcoat.jpg	Clearcoat peeling
Clearcoat bubbles.JPG	Clearcoat bubbling
Clearcoat flaking.jpg	Clearcoat flaking

Cause:

Improper adhesion of clearcoat

Remedy:

Refinish affected areas according to WIS and approved paint manufacturer instructions.

Please use damage code 98081L6