



**Connection hole in soft top canvas with
manufacture data up to 22.02.07**

- 1 Attach short elastic band (1) to old
connection hole on rear window mount
(2).



P77.31-2216-01



P77.31-2217-01